

NEWFOUNDLAND AND LABRADOR

BOARD OF COMMISSIONERS OF PUBLIC UTILITIES

120 Torbay Road, P.O. Box 21040, St. John's, Newfoundland and Labrador, Canada, A1A 5B2

E-mail: gyoung@nlh.nl.ca

2014-09-03

Mr. Geoffrey Young Senior Legal Counsel Newfoundland and Labrador Hydro P.O. Box 12400 St. John's, NL A1B 4K7

Dear Mr. Young:

Re: Newfoundland and Labrador Hydro - 2015 Capital Budget Application -**Requests for Information**

Enclosed are Information Requests PUB-NLH-1 to PUB-NLH-42 regarding the above noted application.

If you have any questions, please do not hesitate to contact the Board's Legal Counsel, Ms. Jacqui Glynn, by email, jgylnn@pub.nl.ca or telephone, (709) 726-6781.

Board Secretary

/cpj Encl.

Newfoundland Power Inc.

Mr. Gerard Hayes, E-mail: ghayes@newfoundlandpower.com

Island Industrial Customer Group

Mr. Paul Coxworthy, E-mail: pcoxworthy@stewartmckelvey.com

Mr. Dean Porter, E-mail: dporter@pa-law.ca

Praxair Canada Inc.

Mr. Dave Meade, E-mail: dave meade@praxair.com

Ms. Sheryl Nisenbaum, E-mail: sheryl_nisenbaum@praxair.com

Sierra Club Canada

Mr. Fred Winsor, E-mail: winsorf@nl.rogers.com

Consumer Advocate

Mr. Thomas Johnson, E-mail; tjohnson@odeaearle.ca

Ms. Colleen Lacey, E-mail: clacey@odeacarle.ca Vale Newfoundland and Labrador Limited

Mr. Tom O'Reilly, E-mail: toreilly@coxandpalmer.com

Mr. Mark Sheppard, E-mail; Mark Sheppard@vale.com

Mr. Danny Dumaresque

Mr. Danny Dumaresque, E-mail: danny.liberal@gmail.com

Mr. William Kennedy, E-mail:wkennedy@kennedylawoffice.ca <u>Grand Riverkeeper* Labrador Inc.</u> Ms. Roberta Frampton Benefiel, E-Mail: rebnfl@gmail.com

1	<u>IN TH</u>	E MATTER OF		
2	the <i>Ele</i>	ctrical Power Control Act, 1994,		
3	SNL 1	994, Chapter E-5.1 (the "EPCA")		
4	and the	and the Public Utilities Act, RSNL 1990,		
5	Chapter P-47 (the "Act"), as amended, and			
6	regulat	ions thereunder; and		
7				
8	IN TH	E MATTER OF		
9	an App	olication by Newfoundland and Labrador Hydro		
10	for an	Order approving:		
11				
12	1)	its 2015 capital budget pursuant to s.41(1) of the Act;		
13	2)	its 2015 capital purchases and construction projects in		
14		excess of \$50,000 pursuant to s.41(3)(a) of the Act;		
15	3)	its leases in excess of \$5,000 pursuant to s. 41(3)(b)		
16		of the Act;		
17	4)	its estimated contributions in aid of construction for		
18		2015 pursuant to s.41(5) of the <i>Act</i> .		

PUBLIC UTILITIES BOARD REQUESTS FOR INFORMATION

PUB-NLH-1 to PUB-NLH-42

Issued: September 3, 2014

2 1 General Ź 3 **PUB-NLH-1** Load growth in the isolated communities necessitating capital expenditures 4 appears to be related to the installation of electric heat. In light of the subsidy 5 being paid by other customers has Hydro had discussions with government 6 relating to the use of electricity as a heating source in isolated diesel 7 communities? 8 9 Volume I, Tab 2015 Capital Plan, Appendix A, page A2 10 11 PUB-NLH-2 In its Capital Plan Hydro anticipates capital expenditures for 2015 of 12 \$274,249,300. Please provide details of the challenges this presents from a 13 resource perspective and how Hydro intends to overcome these challenges. 14 15 Volume I, Tab Holyrood Overview, page 6: Hydro states that: "Initially and until the 2020-2021 timeframe, the plant will function as a fully capable standby facility during the early 16 years of operation of the Muskrat Falls Generating Plant and the LIL between Labrador and 17 Newfoundland. In this capacity, it can be called upon to provide energy and capacity to the 18 19 Island in the event of a loss of supply from Labrador," 20 21 **PUB-NLH-3** Further to the response to PUB-NLH-2 filed with Hydro's 2014 Capital 22 Budget Application, has a plan now been developed with regard to how the 23 Holyrood plant will be operated as a standby facility? If yes, please provide a 24 copy. If no, when is the availability of this plan anticipated? 25 26 PUB-NLH-4 How long will it take to convert the Holyrood plant from a standby facility to 27 a generating facility? 28 29 C-5; Volume I, Tab 2: Replace Interior Coating on Surge Tank 3. On page 4 Hydro states: 30 31 32 33 34

"In particular, the interior coating on the riser is in a deteriorated condition with corrosion evident, A complete coating failure on the interior of the surge tank has left the metal exposed and corroded." However, on page A8 the Hatch report states: "The internal inspection revealed that the coating system on the interior of the tank roof, shell, bowl and riser is in good condition with some minor localized breakdown."

PUB-NLH-5 Please explain how Hydro determined that a complete interior coating failure had occurred which requires refurbishment of all interior surfaces.

35 36

37

38 39

40

41 42

43

44 45 PUB-NLH-6 Has Hydro evaluated other options, such as refurbishing localized areas of coating breakdown?

Recommendation #2 on page A9 the Hatch report states: "Complete a detailed assessment of the tank interior coating system with a certified NACE inspector within the next two years. Implement a program whereby a detailed inspection of the tank interior coating system is performed every four to six years, coordinating with planned unit outages. During each

1 2 3	assessment, refurbish localized areas of coating breakdown on the interior of the table bowl and riser and apply a compatible coating system."		
4 5 6 7	PUB-NLH-7	Has Hydro completed a detailed assessment of the interior coating system with a certified NACE inspector? If yes, please provide a copy of assessment report. If no, why not?	
8 9 10 11	PUB-NLH-8	How will Hydro address the recommendation that a detailed inspection program be implemented and performed every four to six years, coordinating with planned unit outages?	
12 13 14 15 16	In response to PUB-NLH-11 filed with the 2014 Capital Budget Application Hydro states: "Hydro will address the recommendation to remove the existing CP system and all associated components as part of the scope of work for a separate capital project which is in the capital plan for 2015 under the heading "Refurbish Surge Tanks – Bay d'Espoir."		
17 18 19	PUB-NLH-9	Please provide an update regarding the removal of the Cathodic Protection System and associated components for Surge Tank 3.	
20 21	C-7; Volume I, Tab 3: Overhaul Turbine Valves Unit 1 - Holyrood		
22 23 24 25 26	PUB-NLH-10	On page 10, Table 4: Overhaul Maintenance History shows valve overhauls in 2009 and 2006 costing \$607,000 and \$483,000 respectively. Please provide details on why the proposed valve project for 2015 is budgeted at \$1,577,500, an approximate 160% increase from 2009.	
27 28	C-9; Volume I,	Гаb 4: Rehabilitate Salmon River Spillway – Bay d'Espoir	
29 30 31 32	PUB-NLH-11	How does Hydro intend to address the recommendation on page A25 of the Hatch report concerning investigation of the requirement to install gate heating systems on Spillway gates 1 and 3?	
33 34 35	PUB-NLH-12	Please provide a detailed map of the Bay d'Espoir watershed area showing all control structures, spillways, dykes, dams, etc.	
36 37	C-11; Volume I,	Tab 5: Upgrade Powerhouse Roofing - Holyrood	
38 39 40	PUB-NLH-13	Please provide a legible copy of Appendix A Table 4 - Condition Summary and Risk Assessment.	
41 42	C-15; Volume II	, Tab 7: Upgrade Access Road – Cat Arm	
43 44 45	PUB-NLH-14	Does Hydro have an established criteria for assessing the condition of roads? If yes, please provide. If no, how does Hydro provide consistency in road evaluations?	

1	C-19; Tab 9: Up	grade Generator Bearings Units 1 and 3 – Bay d'Espoir	
2 3 4 5	PUB-NLH-15	Please provide an update of the work to be completed in 2014 within this program as approved in Board Order No. P.U. 4(2013).	
6 7 8 9 10	Hydro states: "I deluge system di also states: "The	I, Tab 10: Automate Generator Deluge Systems – Bay d'Espoir, page 6, in 2010 during the rewind of Unit 2, it was noted that the sprinkler ring in the d not have proper holes drilled in the pipe ring to discharge water." Hydro are is a concern that this condition may exist in other units, and to inspect this be generating unit will be required to be partially dismantled."	
12 13	PUB-NLH-16	Please provide an update on the work completed to date within this program.	
14 15 16 17	PUB-NLH-17	Please explain the inspection process of the sprinkler distribution rings prior to the installation of the automated deluge systems to ensure proper holes are drilled to discharge water.	
18 19 20	PUB-NLH-18	Please provide a brief history of the program explaining why changes to the original plan have occurred.	
21 22 23 24	C-29; Volume II, Tab 14: Upgrade Power Transformers, page 17, Hydro states: "Based on the findings of the report, several recommendations have been made, when implemented, would reduce the likelihood of another failure."		
25 26 27	PUB-NLH-19	What are the recommendations and how do they relate to the work to be undertaken in this project?	
28 29 30 31 32	PUB-NLH-20	Please provide a table showing each transformer to be upgraded in this project, the specific work that will be undertaken on each transformer, and the cost, taken from a breakdown of the total cost for 2015 and 2016 shown on Table 11, page 23, that can be attributed to each upgrade on each transformer.	
33 34 35 36 37	regulatory amen allow their use	Page 18, Hydro states: "Hydro, through CEA, is lobbying Environment Canada to have described amendment for scaled equipment such as instrument transformers and bushings to allow their use until 2025. Hydro's current budget is based upon receiving a regulator amendment to 2025."	
38 39	PUB-NLH-21	Please provide an update to the request for a regulatory amendment.	
40 41 42	PUB-NLH-22	If this amendment is not approved how will it affect Hydro's 2015 capital budget?	
43 44 45	"The American	, Tab 17: Inspect Fuel Storage Tanks – Various Sites, page 4, Hydro states: Petroleum Institute (API) recommends that above ground fuel storage tanks nal inspection every ten years after its initial service date." Hydro also states:	

2 identified in the	vill ensure that the tanks are inspected in accordance with the requirements API 653 standard."
3 4 PUB-NLH-23 5 6 7	Please provide an explanation of the Fuel Storage Tank Inspection Plan located in Appendix B page B2 and explain how this supports a 10 year inspection plan.
9 be mitigated by	II, Tab 18: Increase Fuel Storage – Rigolet, page 3, Hydro states: "This will the purchase and installation of a temporary 90,800 Litre self-dyking fuel tank mmer of 2014. The project proposal for this work will be submitted in a pplication."
3 PUB-NLH-24	What is the status of this proposed supplemental application?
5 PUB-NLH-25 6 7	Please provide the current Load Forecast and the Load Forecast which first indicated a deficiency in fuel storage.
8 PUB-NLH-26 9 60	Based on the Load Forecasts provided in PUB-NLH-25 please explain why the storage deficit was not anticipated in earlier planning studies thus eliminating the need for a temporary storage unit.
2 C-48; Volume	II, Tab 20: Replace Accommodations and Septic System – Ebbegunbaeg
23 24 PUB-NLH-27 25	How often are Hydro employees required to perform work at Ebbegunbaeg and what is the typical duration of their stay on site?
26 27 C-53; Volume 28	II, Tab 22: Replace Unit 2038 – Mary's Harbour
PUB-NLH-28 0 1 2	The response to PUB-NLH-020 of Hydro's 2014 Capital Budget Application discusses a long-term supply study for Labrador South, including Mary's Harbour. What is the status of this report? If complete, please provide a copy.
3 PUB-NLH-29 4 5	What is meant by "isolation and icing operational issues with cooling systems" as stated on page 4.
6 C-55; Volume	II, Tab 23: Overhaul Diesel Engines – Various Sites
7 8 PUB-NLH-30 9 .0 .1	Page 7, Table 2 shows SAIDI numbers for 2012 for St. Brendan's, 16.633, and Charlottetown, 22.268, that are higher than the others for the Central and Northern regions, respectively, and for 2011 and 2013, respectively. Please provide details of the incidents that have caused these numbers.
3 C-57; Volume	II, Tab 24: Install Transformer On Line Gas Monitoring – Various Sites
.4 .5 PUB-NLH-31 .6	Does Hydro intend to continue sampling for dissolved gas analysis after the on line gas monitoring systems have been installed on transformers?

1 2 3	PUB-NLH-32	If Hydro does intend to continue sampling, is it Hydro's intention to continue sampling on an annual basis or to change the frequency of sampling to a more or less frequent schedule? Please provide reasons for Hydro's decision.
5	C-59; Volume II	I, Tab 25: Construct Second Distribution Feeder – Nain
6 7 8 9	PUB-NLH-33	Please explain what happened in 2011 to cause the significant increase in Net Energy (MHh) as displayed in Figure 2: Nain System Load History 2009-2013.
10 11	C-61; Volume II	I, Tab 26: Install Automated Meter Reading – Various Sites
12		-y
13 14	PUB-NLH-34	Please provide a description of the new Landis + Gyr's PLX system and its capabilities.
15		
16 17	"The manufactu	I, Tab 27: Replace Programmable Logic Controllers, page 11, Hydro states: were indicates that there is no maintenance agreement in place. Discussion will
18	have to be unde	rtaken within Hydro to determine to what level, if any, of technical support
19 20	from the manufa	acturer is warranted."
20 21 22	PUB-NLH-35	Please provide details of any maintenance or support arrangements Hydro has established for Programmable Logic Controllers.
23 24	C-65; Volume II	I, Tab 28: Line Depot Condition Assessment and Refurbishment
25		
26 27 28	PUB-NLH-36	Has Hydro given any consideration to the requirements of the HVdc transmission line in relationship to its current line depot locations?
29 30 31 32 33	PUB-NLH-37	Please provide a table showing the sites that will be refurbished in this project (Springdale, Cow Head, and Rocky Harbour) and the cost of refurbishment that can be attributed, from a breakdown of Table 1 on page 8, to each of these sites.
34	D-43. Volume I	: Install Hydrometeorological Stations, page D-47, Hydro states: "In 2009,
35		of the program, meteorological stations were installed at the Burnt Dam
36	Spillway and th	e Hinds Lake Control Structure as approved by Board No. P.U. 36(2008).
37	Installation of a	third station at Victoria Reservoir was postponed, because it was to include a
38		ter equivalent sensor. It was prudent to ensure successful operation of the first
39	installation befo	ore deploying the technology at additional sites. The 2010 program was to
40		al snow sensors and was also postponed pending additional experience with
41	the Cat Arm inst	tallation."
42 43	PUB-NLH-38	Plance describe the leggons loomed by Hydro from the normal-time of the
43 44	1 OD-MUU-30	Please describe the lessons learned by Hydro from the completion of this

1	D-289; Volume I: Upgrade Control Wiring Phase 1 to Terminal Station 1		
2			
3	PUB-NLH-39	Please confirm the remaining useful life of the control cables to be replaced.	
4	****** *** ** 40		
5	PUB-NLH-40	Please explain why the repair of the damaged Junction Box B was not a	
6		viable option.	
7			
8	H-1, Volume I: (Capital Expenditures 2010-2019. As per page H-1 the 2014 budget amounts	
9	for Generation and Transmission and Rural Operations is \$144,087,000 and \$126,387,000		
10		in the 2015 Capital Plan, Appendix A, page A2, the budget amounts	
11			
12	Expended to 2014 for Generation and Transmission and Rural Operations is \$111,096,200 and \$59,127,700 respectively.		
	anu \$33,127,700	respectively.	
13	DIID NIL II 44		
14	PUB-NLH-41	Please list the anticipated projects and amounts under these categories for	
15		2014 that are not included in the 2015 Capital Plan, Appendix A listing.	
16			
17	PUB-NLH-42	What are the anticipated capital expenditures for Transmission and Rural	
18		Operations and Generation for 2014, including all projects currently	
19		approved, filed but not approved and projects soon to be filed.	
**		approved, mod out not approved and projects soon to be med.	

DATED at St. John's, Newfoundland this 3rd day of September, 2014.

BOARD OF COMMISSIONERS OF PUBLIC UTILITIES

Cheryl Blyndon
Board Secretary