

**PORT UNION**  
**OPERATOR'S DAM SAFETY INSPECTION**  
**CHECKLIST**

Whirl Pond Dam

Date: Jun 05, 2001

Water Level:	<u>8.16'</u>
Weather:	<u>Sunny &amp; cloudy periods</u>
Upstream Face:	<u>Needs repair</u>
Dam Rockfill:	<u>Needs repair</u>
Gate Opening:	<u>25"</u>
Gate Operation:	<u>OK</u>
Gate cribbing and ballast (include picture):	<u>OK</u>
Fish Screen:	<u>OK</u>
Spillway concrete:	<u>OK</u>
Spillway leakage measurement:	<u>Some leakage</u>
Comments:	<u></u>