

1 **Q. SUBSTATIONS**

2
3 **PUB 33.0 (RE: B-19, Replacement and Standby Substation Equipment)**

4
5 **PUB 33.2**

6 **Explain how safety, or the reliability of the electrical system, has been negatively**
7 **impacted by the lack of operating voltmeters at Twillingate and Garnish.**

8
9 A. The replacement of recording voltmeters at the Twillingate and Garnish Substations is
10 required to identify and monitor voltage levels on the electrical system and allow the
11 Company to address voltage quality concerns.

12
13 Maintaining an adequate voltage level at the customer's premise helps ensure the safe
14 and reliable operation of electrical equipment owned by the customer.