| 1 | Q. | SUBSTATIONS |
|----|----|--|
| 2 | | |
| 3 | | PUB 4.0 (RE: p. 17 & 18 of 73) Rebuild Substations (\$351,000) |
| 4 | | |
| 5 | | PUB 4.2 |
| 6 | | What was the cost of constructing each of these existing weather enclosures? |
| 7 | | |
| 8 | A. | The existing weather enclosures were included as part of a factory-constructed modular |
| 9 | | assembly when the high voltage breakers, protective relaying, switches and ancillary |
| 10 | | equipment were purchased. Consequently, separate cost information is not available for |
| 11 | | the original enclosures. |
| 12 | | |
| 13 | | It is typical to have the weather enclosures included when assembling new substation |
| 14 | | equipment of this type. In this instance, however, the enclosed equipment is in good |
| 15 | | condition, and it is only necessary to replace the enclosures. |
| | | , |