1	Ų.	<u>SUBSTATIONS</u>
2		
3		PUB 4.0 (RE: p. 17 & 18 of 73) Rebuild Substations (\$351,000)
4		
5		PUB 4.3
6		In what year was it determined that these structures were no longer appropriately
7		protecting the enclosed equipment?
8		
9	A.	Provision had been made in the Company's 2004 capital budget to undertake minor
10		refurbishment of these enclosures. However, when the refurbishment was undertaken
11		this year, it was discovered that the extent of the deterioration was much greater than the
12		visual inspection of the enclosures had revealed, and that the structures could no longer
13		provide adequate protection from the weather.