## Q. 2004 CAPITAL EXPENDITURE STATUS REPORT

information.

2 3 4

5

1

**PUB 68** Note 23 Additions to Real Property - Variance: \$97,000

6

7 8

9 10

11 12 A. The table below provides a detailed summary of the projects that contributed to the forecast variance from budget for the Additions to Real Property category for 2004.

Identify any variations from the original budget. Include details of the

identification of the need for each project, the reason for the undertaking at this

time of this particular project, the total cost of each project, and any other relevant

## **Additions to Real Property** 2004 Variances

	Original	2004	
Project	Budget	Forecast	Variance
1) Automatic door openers - Duffy Place	\$0	\$12,500	\$12,500
2) Elevator upgrades - Kenmount & Duffy	0	7,000	7,000
3) Fire suppression system upgrade - Kenmount	0	10,600	10,600
4) Mechanical Maintenance Shop - Duffy Place	0	49,000	49,000
5) Electrical Maintenance Facility - Topsail Road	20,000	38,000	18,000
Totals	\$20,000	\$117,100	\$97,100

13

14

15 16 17

18 19 20

21

22 23 24

25 26 27

28

29

30

3) Fire Suppression System - Additional smoke and fire alarms are being installed to enhance fire detection for the Kenmount Road building on the recommendation of the Company's property insurance inspectors.

1) Automatic Door Openers (Duffy Place) - Three automated doors were installed between the Stores and Metering areas at the Duffy Place facility. These installations were required to improve traffic flow and workplace safety for Storekeepers

The following information is provided regarding the need for each project and the reason

2) Elevator Upgrades - Infrared motion detection devices were installed in the elevator doors at both the Kenmount Road and Duffy Place buildings to address deficiencies that had resulted in two separate personal safety incidents whereby people were hit by the closing elevator doors.

for undertaking the projects at this time:

transporting materials.

- 4) Mechanical Maintenance Shop Duffy Place Some renovations were required in 2004 to accommodate the installation of office furniture and workstations for additional staff assigned to work on the Asset Management initiative for the Generation group. Additional expenditures to complete these renovations are proposed in the 2005 Capital Budget Application.
- 5) <u>Electrical Maintenance Facility (Topsail Road)</u> The original renovation plan for the Topsail Road facility involved the installation of a retractable enclosure. However, as a result of the reprioritization of activities at the facility, particularly the Asset Management initiative, other renovations were required to provide additional office space and an acceptable work environment for staff of the Substation group.