1	Q.	In the report "Rose Blanche Hydro Plant Turbine No. 1 Refurbishment", in
2		Schedule C, Section 2.3, page 4, it is written "To prevent future overheating of the
3		mechanical components of the runner assembly, a new cooling water system supplying
4		the seal areas, complete with dedicated flow switches, will be installed. In addition, a
5		more sensitive non-contact shaft vibration monitoring system will be installed for
6		improved protection of the unit."
7		
8		Will the new dedicated flow switches provide adequate protection to prevent the
9		damage caused by the failure/blockage of the cooling water line from happening
10		again?
11		
12	A.	Please see the response to Request for Information NLH-NP-002.