

1 Q. Re: Burnt Spillway Refurbishment Volume II (Tab 6)

2 At page 1 Hydro states that "...order No. P.U.B. 38 (2010) indicated that for future
3 work at the Burnt Dam Spillway Hydro would have to provide updated evidence
4 from that which was provided in its 2011 Capital Budget Application." Appendix A
5 outlines a report from Hatch dated May 22, 2009. Has this been updated?

6

7

8 A. To provide updated evidence Hydro contracted a service company, Weir Power and
9 Industrial Services, that specializes in hydro generation gate inspection and
10 refurbishment work. In preparing the report, a gearbox service technician visited
11 the site to perform an external visual inspection and also a boroscope inspection
12 that provided limited internal inspection that could be completed during a short
13 equipment outage. A copy of Weir's report is provided in Appendix B to the report.
14 To perform a thorough inspection the gear boxes and hoists need to be removed
15 and sent to a service center. For additional information please refer to the response
16 to CA-NLH-11.