

1    Q.    On page 12 of the Upgrade Transmission Line Corridor Report it is noted that high  
2           side disconnects are used instead of breakers on multiple transformers attached to  
3           the same bus. Does Hydro have a plan developed to replace these disconnects with  
4           breakers? If yes, explain the plan in detail.

5

6

7    A.    Please refer to Hydro's response to CA-NLH-019.