

1 Q. **Project C-11, Upgrade Shoreline Protection – Cat Arm**

2 At page 4 of the report filed at Volume I, Tab 3, Hydro states that:

3 “Extreme environmental conditions in the area have damaged the shoreline
4 protection barrier along an 80m section. These conditions and this type of
5 damage were unforeseen during original construction.”

6 Please provide any correspondence, engineering reports or other documentation
7 generated or received, not already provided with Hydro’s Application, relating to
8 the shoreline protection barrier from when it was first designed and constructed to
9 date, including without limiting the foregoing any such documentation which
10 considered wind/wave action upon the intended barrier.

11

12

13 A. While Hydro has completed surveys of the roadway embankment to monitor the
14 loss of material, no further correspondence, engineering reports or documentation
15 is available. The shoreline protection upgrade requirements are based solely on the
16 recommendations brought forth in the 2010 AMEC report provided with Hydro’s
17 application.