

1 Q. **Reference: Volume II, Distribution System Upgrades (2020 – 2021) – Various, Tab 10, Appendix**
2 **B, page B-7, lines 10 to 14**

3
4 The first 2.3 km section of this feeder has substandard #2 Aluminum conductor.
5 This section has many long span structures that are susceptible to conductor
6 galloping and failure. Most of the structures of this section are located off road
7 and required to be rerouted to roadside for better access (see Figure B- 8).
8 Recent inspections have identified 11 deteriorated poles and two decayed or
9 damaged cribs on this section.

10
11 How many poles are located off road, and what percentage of these poles are deteriorated?

12
13
14 A. There are total 28 poles in this off-road section of line. Approximately 40% of these poles are
15 deteriorated.