

1 **Q. 2004 CAPITAL EXPENDITURE STATUS REPORT**

2
3 **PUB 51 Note 8 Transformer Cooling Refurbishment - Variance: (\$105,000)**

4
5 **Which of the four locations (Greenspond, Bishops Falls, Cobbs Pond and Humber)**
6 **set out in the 2004 Capital Budget were affected by the decision to reduce the**
7 **number of transformer radiators to be refurbished in 2004?**

8
9 A. Following detailed visual and ultrasound inspections to determine the extent of further
10 deterioration following the initial assessment of radiator replacement requirements,
11 Newfoundland Power determined that the radiator replacement scheduled for the Humber
12 T3 transformer could be deferred for a year.