1	Ų.	2004 CAITTAL EXI ENDITURE STATUS REPORT	
2			
3		PUB 52	
4		What effect has the decision to reduce the number of transformer radiators to be	
5		refurbished had on safety, reliability or environmental concerns in the areas	
6		affected?	
7			
8	A.	Newfoundland Power's engineering staff reviewed the condition of the Humber T3	
9		transformer radiators earlier this year, and concluded that the condition of the transformer	
10		radiators was such that their refurbishment could be deferred until 2005 without any	
11		immediate safety, reliability or environmental concerns.	