

1 **Q. 2004 CAPITAL EXPENDITURE STATUS REPORT**

2
3 **PUB 54 Note 8 (sic) Protection and Monitoring Improvements - Variance:**
4 **(\$20,000)**

5
6 **Which of the three locations (Goulds, Gander, Cobbs) set out in the 2004 Capital**
7 **Budget were affected by the decision to reduce the number of tap changer control**
8 **installations scheduled for 2004?**

9
10 A. The reference to Gander Substation on page 24 of 80 of Schedule B to the 2004 Capital
11 Budget Application was the result of a clerical error.

12
13 The location affected by the decision to reduce the number of tap changer control
14 installations scheduled for 2004 was Cobb's Pond Substation, which is located in
15 Gander.