

1 **Q. 2004 CAPITAL EXPENDITURE STATUS REPORT**

2
3 **PUB 56**

4 **Has the company rescheduled the installation of tap changer controls previously**
5 **deferred? If so, until when?**

6
7 A. As noted in the response to Request for Information PUB 55 NP, the planned installation
8 of a newer technology tap changer controller at Cobb's Pond Substation has been
9 deferred as a consequence of the failure and subsequent replacement of the tap changer
10 controller with an older technology unit from the Company's spares inventory.

11
12 The installation of the more advanced tap changer control equipment may be undertaken
13 at Cobb's Pond Substation in the future as part of a broader program to implement
14 remote control of all of the Company's tap changers.