## Page 1 of 1

1	Q.	Re: Upgrade Governor Controls, Unit 1 and 2, Holyrood, Tab <u>3</u> :
2		Have there been any issues with any of the controls for Unit 1 and 2 over the last
3		five years?
4		
5		
ŝ	A.	The controls for Units 1 and 2 have required three electronic module replacements
7		in the last five years. Two of these were required for the Unit 1 controller and one
3		for the Unit 2 controller.