

1 Q. With reference to the Project **C-8, Upgrade Governor Controls Units 1 and 2 –**
2 **Holyrood**, have any of the parts identified in Table 1, at page 5, Volume I, Tab 3,
3 been replaced in the service life to date of either of the Mark V controllers? If yes,
4 identify the part replaced and the year of replacement.

5
6

7 A. The Drive Control, General Electric (GE) Part DS200SDCCG4A, was replaced on Unit
8 1 in 2008 and Unit 2 in 2001. The TC2000 Common Analog I/O, GE Part
9 DS200TCCAG1B, was replaced on Unit 1 in 2009 and Unit 2 in 2001. The Emergency
10 Overspeed Module, GE Part DS200TCEAG1B, was replaced on Unit 2 in 2008. These
11 parts were replaced as a result of failed components in the Mark V Controllers;
12 without the replacements, the generating units are inoperable. These parts do not
13 extend the overall life of the Mark V Controller.