

1 Q. With reference to the Project **C-8, Upgrade Governor Controls Units 1 and 2 –**  
2 **Holyrood**, at page 8, Volume I, Tab 3, Hydro states that there is no maintenance  
3 agreement in place with GE and that maintenance is done by internal plant  
4 resources. What support has GE provided for the Mark V controllers, since their  
5 installation, other than supply of replacement, repair or exchange of components?  
6 Could maintenance by internal plant resources not be continued into the future  
7 and, if no, why not?

8  
9  
10 A. GE provides diagnostic and engineering support for the Mark V controllers. GE has  
11 provided logic and graphic changes for improvements and additions,  
12 troubleshooting assistance and on site calibration services.

13  
14 Maintenance by internal resources will continue in the future. As new  
15 instrumentation technologists are hired, they will need to be properly trained and  
16 this will depend on GE providing the appropriate Mark V training courses in the  
17 future as demand for such training may be reduced.