

1 Q. Were the fuel system or other components involved in this most recent failure of
2 the Hardwoods gas turbine engine included in the life extension upgrade program
3 either as refurbishment or replacement? If no, why not?
4

5

6

7 A. The fuel system components involved in this most recent failure were not included
8 in the life extension upgrade program as either a refurbishment or replacement.

9 The life extension upgrade program scope was based on the recommendations of
10 the *Condition Assessment and Life Cycle Cost Analysis Hardwoods and Stephenville*

11 *Gas Turbine Facilities* report prepared by Stantec in 2007. At that time, these

12 components were deemed by Stantec to be in serviceable condition and were not

recommended for refurbishment or replacement.