

1 Q. NP-NLH-001 Reference: Application, Paragraph 4

2

3 "4. Hydro is proposing to replace the remaining tubing in the lower sections of
 4 the boiler reheaters in Units 1 and 2. Secondary to the tube replacements,
 5 Hydro is proposing additional reliability improvements for the Holyrood TGS.
 6 This includes replacing end of life equipment, including valve and piping
 7 replacements, No. 2 air compressor replacement, pump motor starter
 8 replacements, and heat exchanger replacements, as well as condition
 9 assessments of boiler and feedwater equipment."

10

11 Please complete the following table:

12

Table 1
Capital Expenditure Breakdown

Item	Description	Capital Expenditure
1.	Unit 1 Boiler Reheater Tube Replacements	
2.	Unit 2 Boiler Reheater Tube Replacements	
3.	Valve and Piping Replacements	
4.	No. 2 Air Compressor Replacement	
5.	Pump Motor Starter Replacements	
6.	Heat Exchanger Replacements	
7.	Condition Assessments	
8.	Total	\$11,800,000

- 1 A. Please see Hydro's response to PUB-NLH-005.