

1 **Re Page B-20:**

2 Q. What, if any, efforts have been made to clean out the piping in question so as
3 to prolong its service life?

4

5

6 A. The piping in question was cleaned, due to fouling, and returned to service in
7 the fall of 2001.