

1 Q. **Re: 9, Replace Fuel Oil Heat Tracing – Holyrood \$1,474,300 in 2012, \$1,413,900**  
2 **in future years.**

3 In Volume I, Tab 4, page 11, in the report *Replace Fuel Oil Heating Tracing*, Hydro  
4 states that in 2009 Hydro contacted the original equipment manufacturer (“OEM”)  
5 to determine the cause of the premature repetitive failures experienced from 2004  
6 with the new system. Did the OEM make a recommendation on the type of cables  
7 selected in 2002? If not, who did?

8  
9  
10 A. The OEM, Tyco, provided three options for replacement of the heat tracing systems  
11 in 2002. Please refer to the response to P2-PUB-NLH-44.