

1 Q. Please provide all documentation of the internal inspection of the relevant unit  
2 component parts.  
3  
4

5 A. A third party inspection of the unit was completed between April 28 and May 1,  
6 2014 to evaluate the condition and suitability of the unit for use. The unit was  
7 found to be in good condition, stored in accordance with OEM requirements, and  
8 suitable for use. The inspection report was provided for reference as part of Hydro's  
9 response for GT-DD-NLH-002. Regarding internal inspection of the unit component  
10 parts, this was not necessary as the unit was stored in accordance with OEM  
11 requirements and the unit was still crated and protected in the packaging from the  
12 manufacturing facility.