

1 **B-22 Upgrade Unit 2 Air Preheater Steam Condensate System, \$598,500**

2 Q. Even with the upgrades to Units 1 and 2, do there continue to be instances
3 where condensate stagnation and water hammer occur?

4

5

6 A. There is no noticeable water hammer or stagnation.