Page 1 of 1

1	Q.	Re: Page 6, lines 18-21
2		Provide the asset reliability level assumed for the LIL once it is in service,
3		considering that early-stage reliability may be much lower than the guaranteed
4		level.
5		
6		
7	Α.	A forced outage rate of 1% for the Labrador Island Link (LIL) was used as the basis
8		for the analysis contained in the Near-Term Generation Adequacy Report. This is an
9		approximation for operation of the LIL in monopole metallic return mode as per
10		Section 3.5 of the attached report, initially presented as part of the Island
11		Interconnected System Supply Issues and Power Outages. Now that the LIL is in
12		commissioning and closer to being placed in service, Nalcor is in the process of
13		reviewing and establishing the LIL reliability metrics, in consultation with Hydro, to
14		be used in Hydro's review of planning criteria, scheduled to be filed with the Board
15		in November 2018.
16		
17		Note that in this analysis, the maximum capability of the LIL was limited to 214 MW
18		delivered to the Island Interconnected System. The LIL capacity will be limited to
19		this value until generation at Muskrat Falls is available. As such, for the purposes of
20		this analysis, variance of the forced outage rate have materially less impact on
21		supply adequacy results compared to when the LIL will be fully functioning at 900
22		MW.
23		
24		To further analyze a more stressed system, Hydro presented a sensitivity that
25		considered a one-year delayed in-service of the LIL and limited the capability of the
26		LIL by 50% once available in its Near-Term Generation Adequacy Report filed May
27		22, 2018.

Contract or Purchase Number and Description: LC-G-002 (Project No. 505573) Contractor/Supplier Name: LC-G-002 (Project No. 505573) Document Title: Reliability & Availability Assessment of the HVdc Island Link Total Number of Pages Incl. Front Sheet 32+6 Contractor/Supplier Document Number: Revision Number: EPC(M) Document Number: 505573-480A-47ER-0017 Issue Number: 00 NE-LCP Document Number: ILK-SN-CD-8000-EL-SY-0004-01 NE-LCP Issue Number: B1 Approver's Signature: Jata J Date (dd-mmm-yyyy): 10-Apr-2012 Review Class: Equipment Tag or Model Number: Comments: Entry Review Class: 0 - Review Docs not constitute Approvation Design Detraits, Calculations, test Methods or MATERIAL DEVELOPED AND/OR SELECTED BY THE 0 - REVIEWD AND ACCEPTED - NO COMMENTS, REVISE AND RESUBMIT 0 - REVIEWD AND ACCEPTED - NO COMMENTS Date (dd-mmm-yyy): Area Manages: 0 - NOR REVIEWD Date (dd-mmm-yyy): 2 - Aph - Dai N Area Manages: 2 - Aph - Dai N Date (dd-mmm-yyy): 2 - Aph - Dai N ME-LCP OF CIM- Manages: 0 - NOR REVIEWD Date (dd-mmm-yyy): 2 - Aph - Dai N Area Manages: 2 - Aph - Dai N Date (dd-mmm-yyy): 2 - Aph - Dai N ME-LCP OF EPCIM- Manages: 0 - REVIEWD Date (dd-mmm-yyy): 2 - Aph - Dai N Area Manages: 2 - Aph - Dai N Date (dd-mmm-yyy): 2 - Aph - Dai N ME-LCP OF EPCIM- Manages: 0 - REVIEWD Date (dd-mmm-yyy): 2 - Aph - Dai N Area Manages: 2 - Ap	Doc	ument Front Sheet		nalcor
Contract or Purchase Number and Description: LC-G-002 (Project No. 505573) Contractor/Supplier Name: SNC Lavalia Inc. Document Title: Reliability & Availability Assessment of the HVdc Island Link Total Number of Pages Incl. Front Sheet 32+6 Contractor/Supplier Document Number: Revision Number: BEPC(M) Document Number: S05573-480A-47ER-0017 Issue Number: 00 PPC(M) Document Number: ILK-SN-CD-8000-EL-SY-0004-01 B1 NE-LCP Document Number: ILK-SN-CD-8000-EL-SY-0004-01 B1 Approver's Signature: ILK-SN-CD-8000-EL-SY-0004-01 B1 Approver's Signature: ILK-SN-CD-8000-EL-SY-0004-01 B1 Comments: Equipment Tag or Model Number: Comments: Equipment Tag or Model Number: Comments: Equipment Tag or Model Number: Contractory of the Review Dobs Not constitute Approva. Or Design Detrails, CALCULATIONS, TEST METHODS OR MATERIAL DEVELOPED AND/OR SELECTED BY THE Contractory INCORPORATE COMMENTS, REVISE AND RESUBMIT Equipment Tag or Model Number: Cont Reviewed AND ACCEPTED Date (dd-mmm-yyyy): Area Manager: Date (dd-mmm-yyyy): 27. AAAA-2012 Managements: Date (dd-mmm-yyyy): Area Manager: Date (dd-mmm-yyyy): 27. AAAA-2012 Managements: S.S AAA AAAA General Comments: Date (dd-mmm-yyyy): Area Manager: Date (dd-mmm-yyyy):	[LO	WER CHURCHILL PROJECT
ILC-G-002 (Project No. 505573) SNC Lavalin Inc. Document Title: Reliability & Availability Assessment of the HVdc Island Link Total Number of Pages Incl. Front Sheet 3246 Contractor/Supplier Document Number: Revision Number: S05573-480A-47ER-0017 O0 NE-LCP Document Number: ILK-SN-CD-8000-EL-SY-0004-01 B1 Approver's Signature: ILK-SN-CD-8000-EL-SY-0004-01 Equipment Tag or Model Number: ILK-SN-CD-8000-EL-S		Contract or Purchase Number and Description:	Contractor/Supplie	r Name:
Jocument Title: Total Number of Pages Reliability & Availability Assessment of the HVdc Island Link Incl. Front Sheet 32+6 Contractor/Supplier Document Number: Revision Number: EPC(M) Document Number: Issue Number: 00 VIELCP Document Number: Issue Number: 00 NE-LCP Document Number: Issue Number: 00 NE-LCP Document Number: Issue Number: 01 ME-LCP Document Number: Issue Number: 01 ME-LCP Document Number: Issue Number: 00 Memory Signature: Date (dd-mmm-yyyy): Review Class: Comments: Issue Number: Equipment Tag or Model Number: Wiew Does Nor constitute APPROVALOF DESIGN DETAILS, CALCULATIONS, TEST METHODS OR MATERIAL DEVELOPED AND/OR SELECTED BY THE CONTRACTOR ROW FUL COMPLIANCE WITH CONTRACTOR ROW FUL COM		LC-G-002 (Project No. 505573)	SN	NC Lavalin Inc.
Interactor/ Supplier Document Number: EPC(M) Document Number: Issue Number: 505573-480A-47ER-0017 00 NE-LCP Document Number: 00 ILK-SN-CD-8000-EL-SY-0004-01 B1 Approver's Signature: Date (dd-mmm-yyyy): ILK-SN-CD-8000-EL-SY-0004-01 B1 Comments: Date (dd-mmm-yyyy): Review Does not constitute approval or besion Detraits, calculations, test methods on material Developed and/or selected by the contractor room room room room room room room r	-	Document Title: Reliability & Availability Assessment of the H	HVdc Island Link	Total Number of Pages Incl. Front Sheet 32+6
STOT OUT Issue Number: SO5573-480A-47ER-0017 NE-LCP Document Number: ILK-SN-CD-8000-EL-SY-0004-01 NE-LCP Issue Number: ILK-SN-CD-8000-EL-SY-0004-01 Approver's Signature: Date (dd-mmm-yyyy): Approver's Signature: Date (dd-mmm-yyyy): Comments: Comments: Comments: Review Does nor constitute approval of pesign Detrails, calculations, test methods on material Developed and/or selected by the contractor recomments; OUTRACTOR, NOR DOES IN RELEVE THE CONTRACTOR REMENTS Date (dd-mmm-yyyy): Date (dd-	upplie	Contractor/ Supplier Document Number:		Revision Number:
NE-LCP Document Number: NE-LCP Issue Number: ILK-SN-CD-8000-EL-SY-0004-01 B1 Approver's Signature: Date (dd-mmm-yyyy): Juttill ID-Apr-2012 Comments: Equipment Tag or Model Number: Number: Comments: Equipment Tag or Model Number: ID-Apr-2012 ID-REVIEWE DAD ACCEPTED - NO COMMENTS ID-APROVAL OF DESIGN DETAILS, CALCULATIONS, TEST METHODS OR MATERIAL DEVELOPED AND/OR SELECTED BY THE ID- REVIEWED - NOT ACCEPTED ID-APROVENTS, REVIEWE AND ACCEPTED - NO COMMENTS, REVISE AND RESUBMIT ID- REVIEWED - NOT ACCEPTED ID-APROVENTS, REVIEWED Lead Reviewer: Date (dd-mmm-yyyy): Area Manages: Date (dd-mmm-yyyy); NE-LCP OF EPC(M) Date (dd-mmm-yyyy): Area Manages: Date (dd-mmm-yyyy); Management: ID-Apr-20:10	ictor/Su	EPC(M) Document Number: 505573-480A-47ER-0017		Issue Number: 00
Approver's Signature: Date (dd-mmm-yyyy): Review Class: Approver's Signature: John John John John John John John John	Contra	NE-LCP Document Number:	4	NE-LCP Issue Number:
Approver's Signature: Date (dd-mmm-yyyy): Review Class: Jothuluu 10-Apr-2012 Comments: Equipment Tag or Model Number: Review Does NOT CONSTITUTE APPROVAL OF DESIGN DETAILS, CALCULATIONS, TEST METHODS OR MATERIAL DEVELOPED AND/OR SELECTED BY THE CONTRACTOR, NOR DOES IT RELIEVE THE CONTRACTOR FROM FULL COMPLIANCE WITH CONTRACTUAL OR OTHER OBLIGATIONS. Image: Difference of the contractor of the co	6	ILK-SN-CD-8000-EL-SY-0004-0	1	B1
Comments: Equipment Tag or Model Number: Review Does Not constitute approval of Design Details, calculations, test methods or material Developed and/or selected by the Contractor, Nor Does IT relieve the contractor from Full compliance with contractual or other obligations. Image: Image	NE-L	Approver's Signature: Da	Review Class:	
Solution REVIEW DOES NOT CONSTITUTE APPROVAL OF DESIGN DETAILS, CALCULATIONS, TEST METHODS OR MATERIAL DEVELOPED AND/OR SELECTED BY THE CONTRACTOR, NOR DOES IT RELIEVE THE CONTRACTOR FROM FULL COMPLIANCE WITH CONTRACTUAL OR OTHER OBLIGATIONS. 0 = 0 = -REVIEWED - NOC COMMENTS 0 = 0 = -REVIEWED - INCORPORATE COMMENTS, REVISE AND RESUBMIT 0 = 0 = -INFORMATION ONLY 0 = 0 = -INFORMATION ONLY 0 = 0 = -NOT REVIEWED Lead Reviewer: Date (dd-mmm-yyyy): Area Manager: Date (dd-mmm-yyyy): Area Manager: Date (dd-mmm-yyyy): Area Manager: Date (dd-mmm-yyyy): Area Manager: Date (dd-mmm-yyyy): Management: Date (dd-mmm-yyyy): Management: Date (dd-mmm-yyyy): Date (dd-mmm-yyy): Date (dd-mmm-yyyy): Date (dd-mmm-yyyy): Date (dd-mmm-yyyy): Date (dd-mmm-yyyy): Date (dd-mmm-yyy): Date (dd-mmm-yyyy): Date (dd-mmm-yyyy): Date (dd-mmm-yyy): Date (dd-mmm-yyyy): Date (dd-mmm-yyyy): Date (dd-mmm-yyy): Date (dd-mmm-yyyy): Date (dd-mmm-yyy): Date (dd-mmm-yyyy): Date (dd-mmm-yyyy): Date (dd-mmm-yyyy): Date (dd-mmm-yyyy): Date (dd-mmm-yyyy): Date (dd-mmm-yyyy): Date (dd-mmm-yyyy):		Comments:		Equipment Tag or Model Number:
	NE-LCP or EPC(M)	REVIEW DOES NOT CONSTITUTE APPROVAL OF DESIGN DETAILS, CALCULA CONTRACTOR, NOR DOES IT RELIEVE THE CONTRACTOR FROM FULL COMINIC 01 - REVIEWED AND ACCEPTED - NO COMMENTS 02 - REVIEWED - INCORPORATE COMMENTS, REVISE AND RESUBMI 03 - REVIEWED - NOT ACCEPTED 04 - INFORMATION ONLY 05 - NOT REVIEWED Lead Reviewer: Date (dd-mmm-y 05 - Apr Ja NE-LCP of EPC(M) Management: 25 - Apr Za General Comments:	ATIONS, TEST METHODS OR MATI PLIANCE WITH CONTRACTUAL OF IT (1) Area Manager (1) Area Manager (2) Area Manag	ERIAL DEVELOPED AND/OR SELECTED BY THE R OTHER OBLIGATIONS. Date (dd-mmm-yyyy); 27- APR-2012





Lower Churchill Project

RELIABILITY & AVAILABILITY ASSESSMENT OF THE HVdc ISLAND LINK

SLI Document No.: 505573-480A-47ER-0017-00

Nalcor Reference No.: ILK-SN-CD-8000-EL-SY-0004-01-B1

Date: 10-Apr-2012

Prepared by:	Peter Anderson	L
Verified by:	Ras Marin	
	Rao Atmuri	PROFESSION I
Approved by:	Satish dud	
Approved by.	Satish Sud	Z SATISH SUD ≠
		SIGNATURE
		DATE DATE
		E T

	RELIABILITY & AVAILABILITY ASSESSMENT OF THE HVDC ISLAND LINK		Revision	
SNIC I AVALIN	Nalcor Doc. No.: ILK-SN-CD-8000-EL-SY-0004-01	B1	Date	Page
SINC LAVALIN	SLI Doc.: No. 505573-480A-47ER-0017	00	10-Apr-2012	i

i					
Revision			vision		Remarks
N°	By	Verif.	Appr.	Date	
00	PA	RA	SS	10-Apr-2012	Issued for use



TABLE OF CONTENTS

Page No.

1	INTRODUC	TION	1
	1.1 1.2	Overview of the System Objectives of the Studies	1 3
2	COMPONE	NT RELIABILITY	4
	2.1 2.2 2.3 2.4	HVdc Converter Stations HVdc Line HVdc Submarine Cable Electrode Line	4 7 8 .10
3	COMPOSIT	E SYSTEM	.12
	3.1 3.2 3.3 3.4 3.5	HVdc Overhead Line and Submarine Cable Converters Electrode Lines Complete System Reduced Power Operation	.12 .14 .14 .15 .16
4	CONCLUS	ONS & RECOMMENDATIONS	.18
	4.1 4.2	Conclusions Recommendations	.19 .21
5	REFERENC	ES	.22
AP	PENDIX A		A
	RELIABILIT	Y FORMULAE	A
AP	PENDIX B		В
	CIGRE HIS	TORICAL DATA 1988-2008	B

List of Figures

Figure 1-1: Project Area Map	2
Figure 2-1: Forced Energy Unavailability (FEU) as reported by CIGRE	5
Figure 3-1: Island Link Reliability Connection Diagram1	3

((پ	RELIABILITY & AVAILABILITY ASSESSMENT OF THE HVDC ISLAND LINK		Revision	
SNC ALAVALIN	Nalcor Doc. No.: ILK-SN-CD-8000-EL-SY-0004-01	B1	Date	Page
SINC LAVALIN	SLI Doc.: No. 505573-480A-47ER-0017	00	10-Apr-2012	iii

List of Tables

Table 2-1: Summary of FOR and FU (per terminal)	4
Table 2-2: Converter Unavailability	6
Table 2-3: Converter Reliability (Average 2007-2008)	7
Table 2-4: HVdc Transmission Line Outage Statistics	8
Table 3-1: Reliability Performance of One Pole of the HVdc Line	12
Table 3-2: Composite Island Link Bi-pole Reliability	15
Table 3-3: Reduced Power Capability Modes (Mono-polar)	16
Table 4-1: Converter Reliability (Average 2007-2008)	18
Table 4-2: Reliability Performance of the HVdc Line	18
Table 4-3: Composite Island Link Reliability	19
Table 4-4: Reduced Power Capability Modes	19
Table 4-5: Variation in Overall FOR with DC Overhead Line Repair Time	20

•))	RELIABILITY & AVAILABILITY ASSESSMENT OF THE HVDC ISLAND LINK		Revision	
SNC I AVALIN	Nalcor Doc. No.: ILK-SN-CD-8000-EL-SY-0004-01	B1	Date	Page
JINC LAVALIN	SLI Doc.: No. 505573-480A-47ER-0017	00	10-Apr-2012	1

1 INTRODUCTION

1.1 Overview of the System

This Report presents the results of the reliability and availability analysis carried out to determine the expected performance of the $\pm 350 \text{ kV}$, 900 MW HVdc interconnection between Muskrat Falls and Soldiers Pond (Island Link) [1]. The Maritime Link between Bottom Brook and the Nova Scotia power system was not considered in this study. The results consider the performance of each element of the Island Link as well as the composite reliability of the complete link from Muskrat Falls to Soldiers Pond.

Figure 1-1 provides an overview of the project area.

The assessment considered only the Island Link from the ac bus at the converter station in Muskrat Falls to the ac bus at the Soldiers Pond converter station. The generation at Muskrat Falls, the 315 kV interconnection to Churchill Falls and the synchronous condensers at Soldiers Pond were not included in this assessment since their influence on the reliability of the link itself is considered to be negligible. The number and rating of the synchronous condensers at Soldiers Pond was determined from the steady-state and transient stability analyses and an economic assessment considering single contingency outages of equipment.

	RELIABILITY & AVAILABILITY ASSESSMENT OF THE HVDC ISLAND LINK		Revision	
SNC I AVALIN	Nalcor Doc. No.: ILK-SN-CD-8000-EL-SY-0004-01	B1	Date	Page
SINC LAVALIN	SLI Doc.: No. 505573-480A-47ER-0017	00	10-Apr-2012	2

Figure 1-1: Project Area Map



	RELIABILITY & AVAILABILITY ASSESSMENT OF THE HVDC ISLAND LINK		Revision	
SNC I AVALIN	Nalcor Doc. No.: ILK-SN-CD-8000-EL-SY-0004-01	B1	Date	Page
JINC'LAVALIN	SLI Doc.: No. 505573-480A-47ER-0017	00	10-Apr-2012	3

1.2 Objectives of the Studies

The objectives of this Reliability and Availability (R&A) Assessment are:

- To develop R&A performance indices for the converter stations
- To develop R&A performance indices for the HVdc transmission line from Muskrat Falls to Soldiers Pond
- To assess the R&A performance indices of the submarine cables from Forteau Point to Shoal Cove,
- To develop R&A performance indices for the electrode lines from Muskrat Falls to L'Anse au Diable and from Soldiers Pond to Dowden's Point
- To assess the improvements that could be made in the above indices considering design aspects such as the provision of spare equipment, over-rated equipment, etc.
- To assess the composite R&A performance indices of the complete HVdc Island Link from Muskrat Falls to Soldiers Pond

((پ	RELIABILITY & AVAILABILITY ASSESSMENT OF THE HVDC ISLAND LINK	IENT OF Revision		
SNC ALAVALIN	Nalcor Doc. No.: ILK-SN-CD-8000-EL-SY-0004-01	B1	Date	Page
SINC LAVALIN	SLI Doc.: No. 505573-480A-47ER-0017	00	10-Apr-2012	4

COMPONENT RELIABILITY

This section examines the reliability indicators available for the individual elements within the Island Link: HVdc converter stations, HVdc overhead line, HVdc transition compounds, HVdc submarine cables and electrode lines. An explanation of the reliability calculations used in this assessment is provided in Appendix A.

2.1 HVdc Converter Stations

2

A major input to this assessment was the information compiled by CIGRE on the performance of HVdc converter stations covering 158 terminal-years over the period 1988-2008[2] and the information contained in the PTI report R-64-81 [3]. For the 2-terminal, single-converter-per-pole stations, the following key performance indicators were determined:

- Forced Outage Rate (FOR) in %
- Forced Unavailability or downtime (FU) in hours/year

These indices are for the complete converter including valves, converter transformers, smoothing reactors, filters, etc. The following table summarizes the results, which are shown in detail in Appendix B:

Period	Outage	FOR (%)	FU(hrs/yr)
2007	Pole	0.15	13
	Bipole	0.0003	0.02
2008	Pole	0.38	34
	Bipole	0.0002	0.02
1988-2008	Pole	0.49	43.4
	Bipole	0.003	0.27

Table 2-1: Summary of FOR and FU (per terminal)

The average failure rate per terminal over the period 1988-2008 for pole outages was 2 failures/terminal/year; with an average repair time of 21 hours. The corresponding values for bipole outages were 0.2 failures/terminal/year and 1.3 hours.

	RELIABILITY & AVAILABILITY ASSESSMENT OF THE HVDC ISLAND LINK			
SNC I AVALIN	Nalcor Doc. No.: ILK-SN-CD-8000-EL-SY-0004-01	B1	Date	Page
SINC · LAVALIN	SLI Doc.: No. 505573-480A-47ER-0017	00	10-Apr-2012	5

Thus, for a 2-terminal bipole, the estimated average reliability indicators would be:

- 4 pole outages per year with a repair time of 21 hours per outage (FOR=0.98%)
- 0.4 bipole outages per year with a repair time of 1.3 hours per outage (FOR=0.006%)

The same source also provides information on the breakdown of forced energy unavailability (FEU) into the major components of a converter station: ac equipment and auxiliaries (ACE), thyristor valves (V), dc equipment (DCE), control & protection (C&P) and others (O) as shown in Figure 2-1.



Figure 2-1: Forced Energy Unavailability (FEU) as reported by CIGRE

Breakdown of Average FEU by Equipment Category of all Reporting Thyristor HVdc Systems

The data for 2007-2008 indicate that the major contributors to the energy unavailability of the converter stations are the converter transformers, followed by the dc smoothing reactors. The provision of a spare unit for these major equipment items greatly improves the availability of the complete converter station, as shown in the following illustrative example.

	RELIABILITY & AVAILABILITY ASSESSMENT OF THE HVDC ISLAND LINK		Revision	
SNC I AVALIN	Nalcor Doc. No.: ILK-SN-CD-8000-EL-SY-0004-01	B1	Date	Page
5INC * LAVALIN	SLI Doc.: No. 505573-480A-47ER-0017	00	10-Apr-2012	6

Spare Converter Transformer

λ = Failure rate (1-phase) =	0.01 f/yr
N = No. of Components =	6
R_1 = Repair Time (replacement with spare) =	168 hrs
R_2 = Repair Time at Factory =	4380 hrs

With no spare,

Average outage time per pole

= 0.01x3x4380 = 131 hrs/yr

With one spare (for 6 single phase units), Effective outage time per outage = $R_1+R_2/2 \times [N \lambda R_2/(8760+N \lambda R_2)] = 168+64 = 232$ hrs Average outage time per pole = 0.01x3x232 = 7 hrs/yr

Almost all recent HVdc converter stations have been built with a spare transformer unit of each type and a spare smoothing reactor per terminal. The impact of this design measure is shown by the following CIGRE statistics:

Table 2-2: Converter Unavailability

Item	Performance Indicator				
Spare Transformer		No	Yes	Yes	
Spare Smoothing Reactor		No	No	Yes	
Terminal	Unavailability	3.04%	0.94%	0.21%	
	Hours/ Year	266	82.5	18.6	

Based on the above information, it is recommended that a spare transformer unit of each type and a spare smoothing reactor be provided at each terminal of the Island Link. With spare units at each terminal, the reliability performance indicators of the converter stations can be taken as the average of the 2007 and 2008 statistics from Table 2-1 above since the most recent converter stations were designed with spare units.

((پ	RELIABILITY & AVAILABILITY ASSESSMENT OF THE HVDC ISLAND LINK		Revision	
SNC ALAVALIN	Nalcor Doc. No.: ILK-SN-CD-8000-EL-SY-0004-01	B1	Date	Page
5INC · LAVALIIN	SLI Doc.: No. 505573-480A-47ER-0017	00	10-Apr-2012	7

Table 2-3: Converter Reliability (Average 2007-2008)

Outage	FOR (%)	FU(hrs/yr)	F/yr	Repair Time (hrs)
Pole	0.265	24	1.64	13.8
Bipole	0.00025	0.02	0.24	0.13

With the continuing improvements in the technology and design of converter stations, it would not be unreasonable to expect lower failure rates and repair times for the Muskrat Falls and Soldiers Pond converters. However, for the purpose of this analysis it was considered prudent to use the historical information from the recent past as this would give more conservative results. Insufficient information is available in the historical records to allow for a distinction to be made between each converter at either end of a dc link, one of which may be in a remote area. In the case of the Island Link, the Soldiers Pond converter will be located within a short distance of St. John's, close to the Nalcor headquarters with easy access by road. The Muskrat Falls converter station is within easy access of Happy Valley but if repairs to any converter fault have to be made by staff mobilized from St. John's, then significantly longer repair times would apply to the Muskrat Falls converter. For this assessment, the two converter stations are assumed to be identical.

2.2 HVdc Line

Transmission line outage statistics for HVdc lines are not as readily available as those for ac lines. However, the available outage data of selected projects are presented in Table 2-4 from a compilation of CIGRE statistics produced during the 1990's to provide an indication of the performance of HVdc lines to date. The reporting periods indicated below are the numbers of years for which data was available and do not necessarily represent the total numbers of years in service for each line.

*))	RELIABILITY & AVAILABILITY ASSESSMENT OF THE HVDC ISLAND LINK			
SNC AL AVALUN	Nalcor Doc. No.: ILK-SN-CD-8000-EL-SY-0004-01	B1	Date	Page
SINC LAVALIN	SLI Doc.: No. 505573-480A-47ER-0017	00	10-Apr-2012	8

Table 2-4: HVdd	Transmission Li	ne Outage Statistics
-----------------	-----------------	----------------------

System	Length	Reporting	km-yrs	No. of	f/100km	Avge Duration
	km	Period(yrs)		Outages	/yr/pole	hrs
Pacific Intertie	847	8	6,776	51	0.376	1.48
Nelson River-1	960	11	10,560	45	0.213	0.53
Nelson River-2	960	11	10,560	41	0.194	0.52
Square Butte	749	9	6,741	5	0.037	1.69
CÚ	710	11	7,810	6	0.038	4.72
Itaipu-1	1200	6	7,200	21	0.146	2.06
Itaipu-2	1200	3	3,600	10	0.139	0.24
IPP	784	3	2,352	18	0.383	2.96
Average					0.191	1.78

Using the averages from Table 2-4, for a route length of 1,100 km, the expected reliability performance would be:

- 2.101 outages per pole per year,
- With an average repair time of 1.78 hours per outage

This translates into an unavailability and FOR of 0.0425% per pole.

The common-mode failure of both overhead poles must also be taken into account. It is assumed that this type of failure mode is at least one order of magnitude less likely than a single pole failure but with a longer average repair time and is therefore assumed to have a failure rate of 0.02 f/100km/yr with an average repair time of 24 hrs.

2.3 HVdc Submarine Cable

There is even less information related to the reliability of submarine cables than for overhead dc lines. Cable installations of all types are generally considered to be very reliable since they are installed in a protected environment. However, in the case of submarine cables, the repair time for a cable fault can be extremely long since it involves the mobilization of a repair ship and recovery of the cable, which may not be feasible during certain seasons of the year. The submarine cable crossing of the Straits of Belle Isle is being designed with a spare cable to cover the loss of one cable. Each cable will be rated to carry the rated power of one pole continuously with a 5-minute overload capability of 2xrated power.

SNC I AVALIN	Nalcor Doc. No.: ILK-SN-CD-8000-EL-SY-0004-01	B1	Date	Page
SINC · LAVALIN	SLI Doc.: No. 505573-480A-47ER-0017	00	10-Apr-2012	9

A report by C-Core [4] examined the incidence of iceberg strikes on the submarine cables and concluded that the expected failure rates for such events would be:

- 0.004 failures/year for a single cable
- 0.002 failures/year for 2 cables
- 0.001 failures/year for 3 cables

Repair times for cables in the Strait of Belle Isle could be very long and a repair time of 6 months (4,380 hours) has been assumed. Other cable failures, due to internal failures and other external causes, such as fishing and shipping activities, are assumed to be no worse than 1 in 50 years or 0.02 failures/year. Since there is a spare cable that can be quickly switched to replace a failed cable, the probability of losing a single pole due to a cable fault is the sum of the independent failure of 2 cables plus the probability of an iceberg strike affecting 2 cables. The independent failure of 2 cables can therefore be calculated by:

 $F_{C} = \lambda_{C1} U_{C2} + \lambda_{C2} U_{C1} + \lambda_{C1-2}$ $U_{C} = U_{C1} U_{C2} + U_{C1-2}$

Where λ_{C1-2} , U_{C1-2} represents the failure rate and downtime of 2 cables due to an iceberg strike.

This evaluates to a failure rate of 0.00022 f/yr for the independent failure of 2 cables and 0.002 f/yr due to iceberg strikes, for a total failure rate of 0.0022 f/yr with an average repair time of 4,163 hrs/outage and an average downtime of 9.24 hours/year. This corresponds to an FOR of 0.105%.

For the complete loss of the link, either all 3 cables would need to fail due to independent failure events or an iceberg strike would need to affect all 3 cables. The independent failure mode evaluates to a very small value (9.9E-6 f/yr) and is considered insignificant, leaving a failure of 3 cables due to an iceberg strike as the remaining cause with a failure rate of 0.001 f/yr with an average repair time of 4,380 hours/outage and an average downtime of 4.38 hours/year (An FOR of 0.05%).



RELIABILITY & AVAILABILITY ASSESSMENT OF THE HVDC ISLAND LINK		Revision	
Nalcor Doc. No.: ILK-SN-CD-8000-EL-SY-0004-01	B1	Date	Page
SLI Doc.: No. 505573-480A-47ER-0017	00	10-Apr-2012	10

2.4 Electrode Line

An electrode line will be provided at each converter station to connect to a remote ground electrode. These lines, under bi-pole mode, will carry only the unbalance current between the two poles of the dc line but will also be used at 150% rated pole current during mono-polar operations involving ground return. These lines are essentially medium voltage lines with 2 conductors for redundancy in case of conductor failure and will be continuously monitored for integrity. At the Muskrat Falls end, the electrode line is 400 km in length and at the Soldiers Pond end; it is only 10 km in length.

CEA statistics on transmission equipment performance for ac lines up to 110 kV indicate the average failure rate for such lines to be 5 outages/100km/year with an average repair time of 8.2 hours (downtime = 41 hours/100km/year, 0.47%). Using these values for the Muskrat Falls electrode line would result in 20 outages/year. This appears to be a high value for a line that is continuously monitored and that spends most of its time operating at a voltage well below its rated value. Accordingly, а failure rate equal to one-tenth of this value (i.e. 0.5 failures/100km/year) was assumed and the repair time was kept at 8.2 hours per outage.

For the common-mode failure of both circuits of the electrode line, a failure rate one order of magnitude lower was assumed (i.e. 0.05 failures/100km/year) and the repair time was taken to be the same as for the common-mode failure of both poles of the bipole (i.e. 24 hours). Even with both circuits of the electrode line out of service, it will still be possible to operate the link at rated power with the unbalance current being handled by the station ground or, at worst, running at reduced power in monopolar mode using metallic return.

The electrode line at the Muskrat Falls end (400 km) will either be constructed on a separate wood-pole line or will be installed on the towers of the main dc line itself. It would be reasonable to expect the reliability of the electrode line to be improved if it is mounted on the main line since the majority of common-mode failure events associated with the main line would be the same common-mode failure events

	RELIABILITY & AVAILABILITY ASSESSMENT OF THE HVDC ISLAND LINK	Revision		
SNC I AVALIN	Nalcor Doc. No.: ILK-SN-CD-8000-EL-SY-0004-01	B1	Date	Page
SINC · LAVALIN	SLI Doc.: No. 505573-480A-47ER-0017	00	10-Apr-2012	11

associated with the electrode line. Thus the common-mode failure of the two electrode line circuits is already included in the common-mode failure of the bipole. The impact of this is, however, relatively small.

Given the above considerations, it is considered that the reliability related to the complete loss of the Island Link will not be significantly influenced by the reliability of the electrode lines at either terminal.

•))	RELIABILITY & AVAILABILITY ASSESSMENT OF THE HVDC ISLAND LINK			
CNIC , LANA LINI	Nalcor Doc. No.: ILK-SN-CD-8000-EL-SY-0004-01	B1	Date	Page
SINC · LAVALIIN	SLI Doc.: No. 505573-480A-47ER-0017	00	10-Apr-2012	12

COMPOSITE SYSTEM

3

The composite system reliability of the Island Link can be determined from a consideration of the reliability of the components of the system. The actual connection diagram of the Island Link together with the corresponding connection diagram for the individual components of the reliability is shown in Figure 3-1. The individual poles of the bipole (L1+C+L2) and the converters (CP) are shown as parallel elements since both must fail for the link to fail, while the common-mode failure of the bipole due to a converter fault (BPC or cable/line fault (BPL1, C3 and BPL2) are shown as series elements since any of these failures will result in failure of the link. In all the results tables that are presented in the following sections, the results have been rounded to the appropriate number of significant digits. However, in the actual calculations, the full number of decimal places was retained to ensure the overall arithmetic accuracy of the results.

3.1 HVdc Overhead Line and Submarine Cable

First, it is necessary to determine the composite reliability indices associated with each parallel pole element (L1, C1+2, and L2 in series). Since the failure of any one of these elements will result in the failure of one pole, the failure rate and unavailability of each element can simply be added together as shown in Table 3-1. For each element, the downtime (or unavailability) is the product of the failure rate and the repair time (U= λ .r). Once the total failure rate and downtime have been determined, the repair time can be calculated as r=U/ λ . For the submarine cable, the failure rate, repair time and downtime are those associated with the independent failure of 2 cables and an iceberg strike that impacts 2 cables.

Table 3-1: Reliability Performanc	e of One Pole of the HVdc Line
-----------------------------------	--------------------------------

Element	Failure Rate (f/yr)	Repair Time (hrs)	Downtime (hrs/yr)
L1-388 km	0.741	1.78	1.32
C-Submarine cable	0.0022	4,163	9.24
L2-680 km	1.3	1.78	2.31
Total	2.042	6.3	12.87

	RELIABILITY & AVAILABILITY ASSESSMENT OF THE HVDC ISLAND LINK		Revision	
SNIC I AVALIN	Nalcor Doc. No.: ILK-SN-CD-8000-EL-SY-0004-01	B1	Date	Page
SINC · LAVALIIN	SLI Doc.: No. 505573-480A-47ER-0017	00	10-Apr-2012	13

Figure 3-1: Island Link Reliability Connection Diagram



	RELIABILITY & AVAILABILITY ASSESSMENT OF THE HVDC ISLAND LINK	Revision		
	Nalcor Doc. No.: ILK-SN-CD-8000-EL-SY-0004-01	B1	Date	Page
5INC · LAVALIIN	SLI Doc.: No. 505573-480A-47ER-0017	00	10-Apr-2012	14

The reliability indices for the coincident, independent failure of two poles in parallel are given by:

$$\lambda_{T} = \frac{\lambda_{1} \lambda_{2} (\mathbf{r}_{1} + \mathbf{r}_{2})}{8760} \mathbf{f} / \mathbf{y} \mathbf{r}$$
$$\mathbf{r}_{T} = \frac{\mathbf{r}_{1} \mathbf{r}_{2}}{\mathbf{r}_{1} + \mathbf{r}_{2}} \mathbf{hrs}$$
$$\mathbf{U}_{T} = \lambda_{T} \mathbf{r}_{T} \mathbf{hrs} / \mathbf{yr}$$

From the above composite reliability of each pole, the composite reliability of both poles in independent failure mode is:

$$\begin{split} \lambda_T &= (2.042)^2.(2x6.3)/8760 = 0.006 \text{ f/yr} \\ r_T &= (6.3)^2/(2x6.3) = 3.15 \text{ hrs} \\ U_T &= 0.006x3.15 = 0.019 \text{ hrs/yr} \end{split}$$

In addition, for the complete failure of the link, the probability of an iceberg strike impacting all three submarine cables and the probability of a common mode outage of both overhead line sections must be added to the above independent, coincident failure of both poles.

3.2 Converters

Similarly, the coincident failure of both converters in independent mode can be calculated as:

$$\begin{split} \lambda_T &= (1.64)^2.(2x13.8)/8760 = 0.0084 \text{ f/yr} \\ r_T &= (13.8)^2/(2x13.8) = 6.9 \text{ hrs} \\ U_T &= 0.0086x7 = 0.06 \text{ hrs/yr} \end{split}$$

3.3 Electrode Lines

As mentioned above, the link can still be operated at full power or reduced power even for the complete loss of the electrode line at either end of the link. As such, the reliability of the electrode line is considered to have no significant impact on the composite reliability of the link.

	RELIABILITY & AVAILABILITY ASSESSMENT OF THE HVDC ISLAND LINK		Revision	
SNIC I AVALIN	Nalcor Doc. No.: ILK-SN-CD-8000-EL-SY-0004-01	B1	Date	Page
SINC · LAVALIN	SLI Doc.: No. 505573-480A-47ER-0017	00	10-Apr-2012	15

3.4 Complete System

For the failure of both lines/cables (P1+P2) or both converters (CP+CP), in series with the common-mode failure of both poles due to converter faults (BP) and main line faults (BPL1 and BPL2), the composite reliability of the Island Link is as shown below.

Element	Failure Rate	Repair Time	Downtime	
	(f/yr)	(hrs)	(hrs/yr)	% of Total
BP-Muskrat Falls	0.24	0.13	0.031	0.3
CP+CP-Muskrat Falls	0.0084	6.86	0.057	0.6
BPL1-388 km	0.074	24	1.776	18.6
P1 + P2	0.007	621.7	4.479	46.9
BPL2-680 km	0.13	24	3.12	32.7
CP+CP-Soldiers Pond	0.0084	6.86	0.057	0.6
BP-Soldiers Pond	0.24	0.13	0.031	0.3
Total	0.7078	13.49	9.551	100

Table 3-2: Composite Island Link Bi-pole Reliability

The composite, forced unavailability and FOR is therefore $9.551 / 8760 \times 100 = 0.109\%$.

It is clear from the above results that the major contributors to the unavailability of the Island Link are the common-mode failure of both poles of the overhead line (representing nearly 52% of the total unavailability) and the independent, coincident failure of both poles for the overhead and submarine cable sections (representing 47% of the total unavailability). Of all the values used for the component reliability, the reliability indices associated with common-mode bipole and submarine cable failures are probably the least certain given the relatively small database of operating experience. The parameter that has the most influence on the overall unavailability due to these failures is the repair time required to return a bipole or submarine cable to service after a common-mode failure. The value used in the above analysis was based on the limited operating experience available worldwide which includes bipolar lines of similar length to the Island Link in remote areas with difficult access.

The implied availability from this result is 99.89%. However, it should be borne in mind that this availability value includes periods of time when the full capacity of the link is unavailable. For a pole outage or converter outage or during scheduled

	RELIABILITY & AVAILABILITY ASSESSMENT OF THE HVDC ISLAND LINK		Revision	
SNC I AVALIN	Nalcor Doc. No.: ILK-SN-CD-8000-EL-SY-0004-01	B1	Date	Page
SINC · LAVALIN	SLI Doc.: No. 505573-480A-47ER-0017	00	10-Apr-2012	16

maintenance, the link will be operated in mono-polar mode at a power level up to 150% of rated power per pole on a continuous basis.

3.5 Reduced Power Operation

The scheduled maintenance would typically be of the order of 3 days per pole per year, assuming that maintenance work would be carried out at both terminal stations and on each line (pole) at the same time. With respect to forced periods when the Island Link will not be available for full power transmission, it is necessary to consider only those single contingency events that will result in the loss of one pole of the Island Link. These comprise the loss of a converter at either end or the permanent outage of either pole of the main dc line. Using the values from Table 2-3 for the converters and Table 3-1 for the overhead line and submarine cable components, Table 3-3 shows the reliability indices associated with reduced power modes.

Element	Failure Rate(f/yr)	Repair Time(hrs)	Downtime(hrs/yr)
Scheduled Maintenance	2.0	72	144
Converter-Muskrat Falls	1.64	13.8	22.42
Pole 1	2.04	6.3	12.87
Pole 2	2.04	6.3	12.87
Converter-Soldiers Pond	1.64	13.8	22.42
Total	9.36		214.6

Table 3-3: Reduced Power Capability Modes (Mono-polar)

The composite unavailability and FOR is therefore 214.6 / 8760 x 100 = 2.45%.

Thus, the actual availability of the Island Link at full power capacity is 100-0.109-2.45 = 97.44%.

If the use of the station ground for mono-polar operation is not allowed in the event of the loss of the electrode line, the above values will be increased slightly due to the failure of both conductors of the electrode line. Only the loss of the Muskrat Falls electrode line will be significant since the length of the Soldiers Pond electrode line is relatively short. The coincident failure of both conductors of the Muskrat Falls electrode line was estimated at 0.2 failures/year with an average repair time of

RELIABILITY & AVAILABILITY ASSESSMENT OF THE HVDC ISLAND LINK		Revision		
SNC I AVALIN	Nalcor Doc. No.: ILK-SN-CD-8000-EL-SY-0004-01	B1	Date	Page
SINC · LAVALIN	SLI Doc.: No. 505573-480A-47ER-0017	00	10-Apr-2012	17

24 hours and a downtime of 4.8 hours/year. If these values are added to those shown in Table 3-3 above, the resulting overall FOR increases from 2.45% to 2,51%.

The impact of the repair time for the common-mode failure of both circuits of either the Muskrat Falls electrode line or the main dc line is dominant to the point where the total forced unavailability can be approximated as being proportional to the repair time for such an event. Varying the fault repair time over the range of 3 hours to 10 days, with all other component reliability indices being held constant, the total forced unavailability in % is approximately 2.5/1000 x bi-pole repair time in hours. If a specific reliability performance is required (e.g. total forced unavailability $\leq 0.5\%$), then the repair time for a bi-pole line fault must be kept within 192 hours (8 days). This strong correlation between the unavailability of the link and the repair time associated with common-mode failures of both poles of the main dc line allows the desired reliability to be associated with target repair times. The unavailability of the link at full power, due to single pole forced outages or maintenance, is shared equally by the repair time for one pole and the time required for pole maintenance.

((پ	RELIABILITY & AVAILABILITY ASSESSMENT OF THE HVDC ISLAND LINK	Revision		
SNC I AVALIN	Nalcor Doc. No.: ILK-SN-CD-8000-EL-SY-0004-01	B1	Date	Page
SINC 'LAVALIN	SLI Doc.: No. 505573-480A-47ER-0017	00	10-Apr-2012	18

CONCLUSIONS & RECOMMENDATIONS

<u>Objective 1:</u> To develop R&A performance indices for converter stations

Using historical information compiled by CIGRE from HVdc installations throughout the world over the period 1988-2008, failure rates and repair times were estimated for the converter stations at each end of the Island Link.

Table 4-1: Converter Reliability (Average 2007-2008)

Outage	FOR (%)	FU(hrs/yr)	F/yr	Repair Time (hrs)
Pole	0.265	24	1.64	13.8
Bipole	0.00025	0.02	0.24	0.13

<u>Objective 2:</u> To develop R&A performance indices for the HVdc transmission line from Muskrat Falls to Soldiers Pond

- To assess the improvements that could be made in the above indices considering design aspects such as the provision of spare equipment, over-rated equipment, etc.,
- To assess the composite R&A performance indices of the complete HVdc Island Link from Muskrat Falls to Soldiers Pond.

Element	Failure Rate (f/yr)	Repair Time (hrs)	Downtime (hrs/yr)
L1-388 km	0.741	1.78	1.32
C-Submarine cable	0.0022	4,163	9.24
L2-680 km	1.3	1.78	2.31
Total	2.042	6.3	12.87

Table 4-2: Reliability Performance of the HVdc Line

The associated FOR is 0.147%.

4

	RELIABILITY & AVAILABILITY ASSESSMENT OF THE HVDC ISLAND LINK	Revision		
SNICAL AVALUM	Nalcor Doc. No.: ILK-SN-CD-8000-EL-SY-0004-01	B1	Date	Page
SINC LAVALIN	SLI Doc.: No. 505573-480A-47ER-0017	00	10-Apr-2012	19

Table 4-3: Composite Island Link Reliability

Element	Failure Rate	Repair Time	Downtime	
	(f/yr)	(hrs)	(hrs/yr)	% of Total
BP-Muskrat Falls	0.24	0.13	0.031	0.3
CP+CP-Muskrat Falls	0.0084	6.86	0.057	0.6
BPL1-388 km	0.074	24	1.776	18.6
P1 + P2	0.007	621.7	4.479	46.9
BPL2-680 km	0.13	24	3.12	32.7
CP+CP-Soldiers Pond	0.0084	6.86	0.057	0.6
BP-Soldiers Pond	0.24	0.13	0.031	0.3
Total	0.7078	13.49	9.551	100

The associated FOR is 0.109%. The availability is therefore 99.89%.

Element	Failure Rate(f/yr)	Repair Time(hrs)	Downtime(hrs/yr)
Scheduled Maintenance	2.0	72	144
Converter-Muskrat Falls	1.64	13.8	22.42
Pole 1	2.04	6.3	12.87
Pole 2	2.04	6.3	12.87
Converter-Soldiers Pond	1.64	13.8	22.42
Total	9.36		214.6

Table 4-4: Reduced Power Capability Modes

The associated unavailability is 0.81% due to the forced outage of one pole and 1.64% due to the scheduled maintenance outage of a pole. If the station ground cannot be used for mono-polar operation when the Muskrat Falls electrode line is also unavailable, the total FOR will increase from 2.46% to 2.51%.

4.1 Conclusions

The provision of a spare transformer of each type and a spare smoothing reactor at each converter station will significantly improve the availability of the converters. This has become common practice in recent HVdc schemes.

Using representative reliability data from existing HVdc installations throughout the world, the overall forced unavailability of the complete Island Link is predicted to be approximately 0.1%. The forced unavailability of the full power capability of the Island Link is predicted to be less than 2.5%, with the scheduled unavailability for

	RELIABILITY & AVAILABILITY ASSESSMENT OF THE HVDC ISLAND LINK	Revision		
SNC I AVALIN	Nalcor Doc. No.: ILK-SN-CD-8000-EL-SY-0004-01	B1	Date	Page
SINC · LAVALIN	SLI Doc.: No. 505573-480A-47ER-0017	00	10-Apr-2012	20

maintenance being 1.64%. However, both of the values for forced unavailability are very dependent on the average repair time that can be achieved for pole outages and common-mode failures of both poles of the dc line.

It has been shown that a linear relationship exists between these repair times and the unavailability of the Island Link. Once a target reliability has been decided on, the maximum repair time can be determined. The overall unavailability of the complete link is not sensitive to the repair time for the submarine cables. This is due to the provision of a spare submarine cable across the Strait of Belle Isle and the subsequent very low failure rates for 2 or 3 cables. An increase in the repair time for a common-mode failure of both overhead line sections of the dc line (due to a tower failure, for example) from 24 hours to 2 weeks (336 hours) resulted in an increase in the total unavailability from 0.108% to 0.835%.

Based on the historical data available, the repair time for single pole outages on the overhead line sections was estimated at 1.78 hours/outage, while the repair time for common-mode failure of both poles was assumed as 24 hours. If both these repair times are varied then the overall unavailability will change. The following values of overall FOR were calculated for a range of overhead dc line section repair times (these repair times were used for both independent, coincident failures of both poles and for the common-mode failure of both poles).

Repair Time(hrs)	FOR(%)
24 (1 day)	0.112
48 (2 days)	0.179
72 (3 days)	0.251
96 (4 days)	0.33
120 (5 days)	0.416
144 (6 days)	0.507
168 (1 week)	0.605
336 (2 weeks)	1.463

	RELIABILITY & AVAILABILITY ASSESSMENT OF THE HVDC ISLAND LINK	Revision		
SNC I AVALIN	Nalcor Doc. No.: ILK-SN-CD-8000-EL-SY-0004-01	B1	Date	Page
SINC · LAVALIN	SLI Doc.: No. 505573-480A-47ER-0017	00	10-Apr-2012	21

The relationship is not linear, as may be expected, but does show the dependence of the unavailability on the repair time associated with overhead dc line section faults.

The total unavailability of full power due to a pole outage is determined to a large extent by the scheduled maintenance outage of each pole.

4.2 Recommendations

At each converter station, a spare converter transformer of each type (single phase) and a spare smoothing reactor should be provided. This will significantly improve the availability of the converters.

Other critical components and those items with long lead times should also be considered as items that should be provided with on-site spares. These items are normally determined by the converter supplier in order to meet the specified target reliability and availability values in the converter specification.

•))	RELIABILITY & AVAILABILITY ASSESSMENT OF THE HVDC ISLAND LINK	Revision		
SNC I AVALIN	Nalcor Doc. No.: ILK-SN-CD-8000-EL-SY-0004-01	B1	Date	Page
JINC LAVALIN	SLI Doc.: No. 505573-480A-47ER-0017	00	10-Apr-2012	22

5 **REFERENCES**

- Nalcor Energy-Lower Churchill Project, :Basis of Design, Document LCP-PT-ED-0000-EN-RP-0001-O1.
- 2) A Survey of the Reliability of HVDC Systems throughout the World during 2007 2008,
 M.G. Bennett, N.S.Dhaliwal, A. Leirbukt
 CIGRE 2010 Technical Session, Paris, Paper: B4_209_2010
- Newfoundland & Labrador HVDC Project, HVDC Link Reliability Studies, Power Technologies Inc., Schenectady, NY, Report R-64-81, 11 October, 1981.
- Iceberg Risk to Subsea Cables in the Strait of Belle Isle, C-Core Report ILK-CC-CD-8110-EN-RP-0001-01, June 2011.

	RELIABILITY & AVAILABILITY ASSESSMENT OF THE HVDC ISLAND LINK	Revision		
SNC I AVALIN	Nalcor Doc. No.: ILK-SN-CD-8000-EL-SY-0004-01	B1	Date	Page
SINC · LAVALIN	SLI Doc.: No. 505573-480A-47ER-0017	00	10-Apr-2012	Α

APPENDIX A

RELIABILITY FORMULAE

	RELIABILITY & AVAILABILITY ASSESSMENT OF THE HVDC ISLAND LINK		Revision	
SNC I AVALIN	Nalcor Doc. No.: ILK-SN-CD-8000-EL-SY-0004-01	B1	Date	Page
SINC · LAVALIN	SLI Doc.: No. 505573-480A-47ER-0017	00	10-Apr-2012	A-1

Individual Components

The reliability of any individual component of a system can be expressed in terms of its failure rate (λ), repair time (r), availability (A) and unavailability or downtime (U). These indices are linked in the following relationships:

U = λ . r

A = (1-U)

The failure rate is normally expressed in the number of failures/year, the repair time is normally expressed in hours/repair, availability and downtime are normally expressed in hours/year or in per unit/year where the repair time is divided by 8760 hours/year.

Thus a component with a failure rate of 2 failures/year and a repair time of 24 hours/repair will have a downtime of 2 x 24 = 48 hours/year or 48/8760 = 0.0055 p.u./year (sometimes expressed as 0.55%).

Furthermore, the forced outage rate (FOR) can be calculated as:

 $\mathbf{FOR} = \frac{\mathbf{U}}{1+\mathbf{U}}$, which can be approximated as FOR = U where U is small in relation

to unity.

Components in Series

In a system where the failure of any single component will result in failure of the system, the components are said to be connected in series, using the analogy of an electrical circuit. In such a system, the total system failure rate is simply the sum of the failure rates of the individual components. Similarly, the downtime of the system is the sum of the downtimes of the components.

For example if a system comprises two components, one with a failure rate of 2 failures/year and a downtime of 24 hours/year (repair time = 24/2 = 12 hours/failure); the other with a failure rate of 3 failures/year and a downtime of 12 hours (repair time = 12/3 = 4 hours/failure), the system failure rate will be 5 failures/year with a total downtime of 36 hours/year (repair time = 36/5 = 7.2 hours/failure).

	RELIABILITY & AVAILABILITY ASSESSMENT OF THE HVDC ISLAND LINK		Revision	
SNC I AVALIN	Nalcor Doc. No.: ILK-SN-CD-8000-EL-SY-0004-01	B1	Date	Page
SINC · LAVALIN	SLI Doc.: No. 505573-480A-47ER-0017	00	10-Apr-2012	A-2

Components in Parallel

In a system where multiple components must fail to result in failure of the system, the components are said to be connected in parallel, again using the analogy of an electrical circuit. For a two component system, two possible failure modes can be envisaged: the failure of component 2 while component 1 is in a failed state and the failure of component 1 while component 2 is in a failed state. This is expressed mathematically as follows:

$$\lambda_{\mathsf{T}} = \lambda_2 \cdot \mathbf{U}_1 + \lambda_1 \cdot \mathbf{U}_2 = \lambda_2 \cdot (\lambda_1 \cdot \frac{\mathbf{r}_1}{8760}) + \lambda_1 \cdot (\lambda_2 \cdot \frac{\mathbf{r}_2}{8760}) = \frac{\lambda_1 \cdot \lambda_2 \cdot (\mathbf{r}_1 + \mathbf{r}_2)}{8760}$$
 failures / year

The total downtime is simply the product of the individual downtimes.

 $U_T = U_1 \cdot U_2$

From which the average repair time can be calculated as:

$$\begin{split} \boldsymbol{U}_{T} &= \lambda_{1} \cdot \boldsymbol{r}_{1} \cdot \lambda_{2} \cdot \boldsymbol{r}_{2} \\ \boldsymbol{r}_{T} &= \frac{\boldsymbol{U}_{T}}{\lambda_{T}} = \frac{\lambda_{1} \cdot \boldsymbol{r}_{1} \cdot \lambda_{2} \cdot \boldsymbol{r}_{2}}{\lambda_{1} \cdot \lambda_{2} \cdot (\boldsymbol{r}_{1} + \boldsymbol{r}_{2})} = \frac{\boldsymbol{r}_{1} \cdot \boldsymbol{r}_{2}}{\boldsymbol{r}_{1} + \boldsymbol{r}_{2}} \text{ hours / failure} \end{split}$$

Using the same example used for components in series:

$$\lambda_{\tau} = \lambda_2 \cdot U_1 + \lambda_1 \cdot U_2 = 3 \times 24 / 8760 + 2 \times 12 / 8760 = 0.011 \text{ failures / year}$$
$$U_{\tau} = U_1 \cdot U_2 = 24 \times 12 / 8760 = 0.033 \text{ hours / year}$$
$$r_{\tau} = \frac{4 \times 12}{4 + 12} = 3 \text{ hours / failure or } r_{\tau} = \frac{U_{\tau}}{\lambda_{\tau}} = \frac{0.033}{0.011} = 3 \text{ hours / failure}$$

	RELIABILITY & AVAILABILITY ASSESSMENT OF THE HVDC ISLAND LINK		Revision	
SNC I AVALIN	Nalcor Doc. No.: ILK-SN-CD-8000-EL-SY-0004-01	B1	Date	Page
SINC · LAVALIN	SLI Doc.: No. 505573-480A-47ER-0017	00	10-Apr-2012	В

APPENDIX B

CIGRE HISTORICAL DATA 1988-2008

((+	RELIABILITY & AVAILABILITY ASSESSMENT OF THE HVDC ISLAND LINK		Revision	
INT LAW LAND	Nalcor Doc. No.: ILK-SN-CD-8000-EL-SY-0004-01	B1	Date	Page
NITTEAST. ONIC	SLI Doc.: No. 505573-480A-47ER-0017	00	10-Apr-2012	B-1

CIGRE Historical Data 1988-2008 per Terminal

1s - 1 Converter per Pole	
2 Terminal Systen	

		6	007			2(008			Aver	ade 195	38-2008	
Name	Po	le	Bipol	e	Po	le	Bipol	e	Years	Po	le le	Bip	ole
	þ	dp	đ	qp	fp	dp	ą	qp		fp	dþ	ą	qp
Skagerrak 1 & 2	1.25	3.1	0	0	2	3.8	0.5	~	20	1.54	17.1	0.13	1.03
Square Butte	~	4.1	1.5	0.3	5.25	0.8	0	0	18	2.85	6.2	0.42	2.27
cU	0.5	23.8	0	0	1.25	58.5	0	0	20	1.71	4.6	0.28	1.66
Gotland 2&3	0.25	0.8	0	0	0.5	46.6	0	0	20	0.38	35.8	0.2	1.49
Fennoskan	2	14.2			1.5	46.4			19	2.26	10.1		
SACOI	3.33	1.7			1.67	2.5			16	4.9	2.6		
New Zealand 2	2.5	4.3			0.5	0.7			17	1.65	2.7		
Kontek	0.5	2.7			-	32			7	0.86	15.7		
SwePol	0.5	2.4			0	1.7			œ	3.56	21		
Kii Channel	0	0		0	0	0	0	0	ø	0.16	99.6	0	0
Grita	4	42.2			4.5	9.3			5	2.7	17.1		
Average	1.44	9.03	0.38	0.06	1.83	18.39	0.10	0.20	158	2.05	21.14	0.21	1.29
Downtime (hrs/yr)	13.0		0.02		34		0.02			43.4		0.27	
FOR/U(hrs/yr)	0.15%		0.0003%		0.38%		0.0002%			0.49%		0.003%	

PUB-NLH-009, Attachment 1 Page 32 of 32