

1 Q. Further to the response to PUB-NLH-272, confirm that no load shedding had to be
2 performed to achieve the stability outlined in the response and state the status of
3 the Maritime Link during this study including whether or not curtailment of the
4 Maritime Link was performed.

5

6

7 A. Further to Hydro's response to PUB-NLH-272, no load shedding was performed. The
8 Maritime Link was in service with an export of 158 MW. No curtailment of the
9 Maritime Link was performed.