- The Application states that the failed diesel engine was new when installed in 2019 and had
  10,466 hours of operation. Was the failed diesel engine covered under a warranty? If yes, please
  provide the warranty details. If not, please explain why there was no warranty associated with
  the diesel engine.
- 7 A. The failed diesel engine was purchased with a 12-month warranty, which is the standard
  8 warranty period for CAT for prime power applications. As this engine failed after three years of
  9 service, it was no longer covered under warranty at the time of failure.

6