- Q. Page 21 of the Cost of Service Recovery Evidence by Lorne Henderson states that the company is continuing the process of phasing out mercury vapor lights. Are these lights being removed from the rate base calculation as they are discontinued ore (sic) are they continuing to be amortized?
- 5
 6 A. As mercury vapour lights are removed from service, they are retired and removed from rate base.