

1 **Topsail – Replace Protection and Controls, Volume 2, Appendix 1, page 1 (\$200,000)**
2

3 **Q. Is the 26% unit trips caused by the loss of speed reference signal a Newfoundland**
4 **Power experience or an industry experience?**
5

6 A. The reference to 26% of all unit trips caused by the loss of speed reference signal
7 contained in the Topsail Plant Governor, Protection and Control Systems Engineering
8 Review is based upon Newfoundland Power’s experience at this plant.