

1 Q. Further to PUB-Nalcor-126, with the retirement of these synchronous condensers in
2 2041, what additional equipment will be added to the system to provide the
3 necessary reactive power requirements?
4

5
6 A. While the condition assessment report in PUB-Nalcor-126 addressed the life of
7 Holyrood up to 2041, the report did not discuss or draw conclusions on the
8 potential remaining useful life of the assets at 2041. A decision to refurbish or
9 replace the synchronous condensers will be made prior to 2041.