

1   **Re Page B-56:**

2   Q.    What has been the cost, in the last five years, of the installation of  
3        borosilicate tiles to slow corrosion?

4

5

6   A.    The cost for the last five years is as follows:

7               2006           \$ 280,000

8               2005           \$ 260,000

9               2004           \$ 100,000

10              2003           \$ 200,000

11              2002           \$ 100,000