1 Q. Reference: Project - Upgrade Waste Water Equalization System - Holyrood

Please explain in detail how safety concerns (mold, corrosion) have been addressed or
mitigated, since at least 2014 (when Hydro states this project was first contemplated), when
Hydro or other personnel are required to enter the facility?

6

5

A. Safety concerns have primarily been mitigated by use of PPE.¹ Employees have been donning the respirators required for safe entry as determined from the mold assessments completed in 2011, 2013, and 2016. Additionally, Newfoundland and Labrador Hydro limits entry into the building to those who are required to be there for a specific purpose (e.g., collecting samples) and also requires PPE including hardhats, safety glasses, and steel toe boots for entry into the building.

¹ Personal Protective Equipment ("PPE").