

Newfoundland and Labrador Hydro Hydro Place. 500 Columbus Drive P.O. Box 12400. St. John's. NL Canada A1B 4K7 t. 709.737.1400 l f. 709.737.1800 nlhydro.com

April 26, 2022

Board of Commissioners of Public Utilities Prince Charles Building 120 Torbay Road, P.O. Box 21040 St. John's, NL A1A 5B2

Attention: Ms. Cheryl Blundon

Director of Corporate Services and Board Secretary

Dear Ms. Blundon:

Re: Application for Approval to Purchase Last Stage Blades for Holyrood Thermal Generating Station Units 1 and 2

Please find enclosed Newfoundland and Labrador Hydro's ("Hydro") application for approval to purchase one set of last stage blades to serve as capital spares for Units 1 and 2 at the Holyrood Thermal Generating Station ("Holyrood TGS"). This project is required to support the reliable and safe operation of the Holyrood TGS at full generation capacity until March 31, 2024. The estimated cost of this project is \$1,578,900.

Should you have any questions, please contact the undersigned.

Yours truly,

NEWFOUNDLAND AND LABRADOR HYDRO

Shirley A. Walsh

Senior Legal Counsel, Regulatory SAW/sk

Encl.

ecc:

Board of Commissioners of Public Utilities

Jacqui H. Glynn PUB Official Email

Consumer Advocate

Dennis M. Browne, QC, Browne Fitzgerald Morgan & Avis Stephen F. Fitzgerald, Browne Fitzgerald Morgan & Avis Sarah G. Fitzgerald, Browne Fitzgerald Morgan & Avis Bernice Bailey, Browne Fitzgerald Morgan & Avis Bernard M. Coffey, QC **Labrador Interconnected Group**

Senwung F. Luk, Olthuis Kleer Townshend LLP Joshua H. Favel, Olthuis Kleer Townshend LLP

Newfoundland Power Inc.

Dominic J. Foley Lindsay S.A. Hollett Regulatory Email Island Industrial Customer Group Paul L. Coxworthy, Stewart McKelvey Denis J. Fleming, Cox & Palmer Dean A. Porter, Poole Althouse

¹ In the "Reliability and Resource Adequacy Study Review – Additional Considerations of the Labrador-Island Link Reliability Assessment and Outcomes of the Failure Investigation Findings – Additional Information," Newfoundland and Labrador Hydro, February 4, 2022, p. 7, item 3, Hydro advised the Board of Commissioners of Public Utilities of its decision to extend operation of the Holyrood TGS as a generating facility to March 31, 2024.



Application for Approval to Purchase Last Stage Blades for Holyrood Thermal Generating Station Units 1 and 2

April 26, 2022



An application to the Board of Commissioners of Public Utilities

IN THE MATTER OF the *Electrical Power Control Act, 1994,* SNL 1994, Chapter E-5.1 (*"EPCA"*) and the *Public Utilities Act,* RSNL 1990, Chapter P-47 (*"Act"*), and regulations thereunder; and

IN THE MATTER OF an application by Newfoundland and Labrador Hydro ("Hydro") for approval to purchase one set of last stage blades ("LSB") to serve as capital spares for Units 1 and 2 at the Holyrood Thermal Generating Station ("Holyrood TGS") pursuant to s 41(3) of the *Act*.

To: The Board of Commissioners of Public Utilities ("Board")

THE APPLICATION OF NEWFOUNDLAND AND LABRADOR HYDRO STATES THAT:

A. Background

- 1. Hydro is a corporation continued and existing under the *Hydro Corporation Act, 2007*, is a public utility within the meaning of the *Act*, and is subject to the provisions of the *EPCA*.
- 2. Hydro is the primary generator of electricity in Newfoundland and Labrador. As part of its generating assets, Hydro owns and operates the Holyrood TGS, which has three oil-fired generating units providing an installed capacity of 490 MW. The Holyrood TGS represents approximately one third of Hydro's Island Interconnected System generating capacity and approximately one quarter of the total Island Interconnected System capacity when included with all other customer-owned generation.

B. Application

3. The Holyrood TGS consists of three thermal generating units: Units 1 and 2, each providing a capacity of 170 MW, and Unit 3, providing a capacity of 150 MW. Each thermal generating unit is supplied with steam generated by a dedicated boiler for each unit. The steam is transferred from each boiler through high-energy piping to a steam turbine. Passage of steam through the various stages of the turbine rotor blades converts the energy of the steam into rotational

energy in the turbine, which drives a generator to convert the rotating energy into electrical power.

- 4. Hydro retained Hatch Ltd. ("Hatch"), with support from General Electric ("GE"), to complete the "HTGS Condition Assessment and Life Extension Study." As part of this assessment, in July 2021, Hatch considered the results of major inspections and non-destructive examinations ("NDE") performed on the various stages of the Unit 1 turbine rotor blades as part of the 2021 Unit 1 major turbine overhaul project. The NDE showed a 3/8" linear crack on one of the LSB.
- 5. As detailed in Schedule 1 to this Application, cracking of turbine blades could lead to unacceptable operational vibration in the turbine, forcing the unit offline until replacement of the blades occurs. This could also lead to extensive damage to the unit and possible steam release into the powerhouse. GE, as the original equipment manufacturer, and Hatch recommended inspecting the Unit 1 LSBs within one year of the mitigating weld work that was completed as part of the 2021 Unit 1 major turbine overhaul project. They further recommended the subsequent replacement of the LSBs, the timing of which would be determined by the outcome of the inspection.
- 6. Procurement and installation of LSBs is estimated to take approximately 42–46 weeks; of that, the procurement period is approximately 30 weeks. Procurement of spares to have in place should additional cracks be found on Unit 1 significantly reduces the downtime necessary to replace the part.
- 7. The Holyrood TGS Unit 2 is an identical unit to Unit 1. While there has been no indication of cracks to that Unit's LSB's, Hydro believes that, as it is of identical design and has been subjected to near-identical operating conditions, procurement of the spare LSBs will also mitigate the risk of failure related to that unit.

¹ "Reliability and Resource Adequacy Study Review – Assessment to Determine the Potential Long-Term Viability of the Holyrood Thermal Generating Station," Newfoundland and Labrador Hydro, March 31, 2022, att. 1, att. 2, and att. 3.

-

- 8. On February 4, 2022, Hydro advised the Board that it would be extending the Holyrood TGS readiness to operate to March 31, 2024.² Hydro made the decision to further extend the operations of the Holyrood TGS as a generating station to ensure reliable service for customers while the Muskrat Falls Project assets and the Labrador-Island Link are brought online and proven reliable. Taking steps to procure the spare LSBs at this time is necessary to reduce the risk to the required generation availability of the Holyrood TGS.
- 9. Procurement of one set of turbine LSBs is expected to cost \$1,578,900, with the LSBs received by March 2023.

C. Hydro's Request

- 10. Hydro submits that the proposed capital expenditures detailed above and further described in Schedule 1 to this application are necessary to ensure that Hydro can continue to provide service that is safe and adequate and just and reasonable as required by Section 37 of the Act.
- 11. Hydro requests that the Board make an order pursuant to Section 41(3) of the *Act* approving Hydro's purchase of one set of LSBs to serve as capital spares for Units 1 and 2 at the Holyrood TGS.

D. Communications

12. Communications with respect to this application should be forwarded to Shirley A. Walsh, Senior Legal Counsel, Regulatory for Hydro.

DATED at St. John's in the province of Newfoundland and Labrador on this 26th day of April 2022.

NEWFOUNDLAND AND LABRADOR HYDRO

Shirley A. Walsh Counsel for the Applicant Newfoundland and Labrador Hydro, 500 Columbus Drive, P.O. Box 12400

St. John's, NL A1B 4K7 Telephone: (709) 685-4973

² In the "Reliability and Resource Adequacy Study Review – Additional Considerations of the Labrador-Island Link Reliability Assessment and Outcomes of the Failure Investigation Findings – Additional Information," Newfoundland and Labrador Hydro, February 4, 2022, p. 7, item 3, Hydro advised the Board of its decision to extend operation of the Holyrood TGS as a generating facility to March 31, 2024.



Schedule 1 Holyrood Thermal Generating Station Unit 1 and Unit 2 Turbine Last Stage Blades





Holyrood Thermal Generating Station Unit 1 and Unit 2 Turbine Last Stage Blades

April 26, 2022

hydro

1 Executive Summary

- 2 The Holyrood Thermal Generating Station ("Holyrood TGS") steam turbines are exposed to several
- 3 degradation mechanisms such as fatigue cracking, corrosion, erosion, wear, and creep.
- 4 In July 2021, as part of the "HTGS Condition Assessment and Life Extension Study," a detailed
- 5 assessment of the turbine's last stage blades ("LSB") was completed. The study considered the results of
- 6 major inspections and non-destructive examination ("NDE") performed on the Unit 1 turbine blades,
- 7 completed as part of the 2021 Unit 1 major turbine overhaul project. The NDE showed a 3/8" linear
- 8 crack on one of the LSBs.
- 9 Cracking of turbine blades could lead to unacceptable operational vibration in the turbine, forcing the
- unit offline until replacement of the blades occurs. This could also lead to extensive damage to the unit
- and possible steam release into the powerhouse. General Electric ("GE"), the original equipment
- 12 manufacturer ("OEM"), and Hatch Ltd. ("Hatch") recommended inspecting the LSBs within one year of
- the mitigating weld work, completed as part of the 2021 Unit 1 major turbine overhaul project, as well
- as the subsequent replacement of the LSBs. The timing of the replacement would be determined by the
- 15 outcome of the inspection.
- As Units 1 and 2 are of identical design and have been subjected to near-identical operating conditions,
- 17 Newfoundland and Labrador Hydro ("Hydro") is proposing the purchase of one set of LSBs to serve as
- 18 capital spares for Units 1 and 2.
- 19 This project is required to support the reliable and safe operation of the Holyrood TGS at full generation
- 20 capacity until March 2024. This project was not considered for inclusion in Hydro's "2022 Capital Budget
- 21 Application,"² as the cracking on the Unit 1 LSBs was not known at the time the application was
- 22 finalized. Inclusion in Hydro's "2023 Capital Budget Application" would not provide sufficient time to
- 23 procure spare LSBs before the Unit 2 turbine overhaul in 2023. Hydro, therefore, requests approval of
- 24 this supplemental capital expenditure to enable Hydro to commence procurement in 2022, for delivery
- in advance of the scheduled Unit 2 turbine inspection in 2023.

² "2022 Capital Budget Application," Newfoundland and Labrador Hydro, rev. September 17, 2021 (originally filed August 2, 2021).



¹ "HTGS Condition Assessment and Life Extension Study," Hatch Ltd., March 31, 2022, vol. I and vol. II.

- 1 This project to purchase spare LSBs is planned for completion in 2023 with a project estimate of
- 2 \$1,578,900.



Contents

Execut	tive Summary	i
1.0	Introduction	
2.0	Background	2
2.1	Existing System	2
2.2	Operating Experience	3
3.0	Analysis	4
3.1	Identification of Alternatives	4
3.2	Evaluation of Alternatives	5
3.3	Recommended Alternative	5
4.0	Project Description	6
4.1	Scope	6
4.2	Estimate	6
4.3	Schedule	6
5.0	Conclusion	7



1.0 Introduction

- 2 The Holyrood TGS consists of three thermal generating units: Units 1 and 2, each providing a capacity of
- 3 170 MW, and Unit 3, providing a capacity of 150 MW. Each thermal generating unit is supplied with
- 4 steam generated by a dedicated boiler for each unit. The steam is transferred from each boiler through
- 5 high-energy piping to a steam turbine. Passage of steam through the various stages of the turbine rotor
- 6 blades converts the energy of the steam into rotational energy in the turbine, which drives a generator
- 7 to convert the rotating energy into electrical power.
- 8 Hatch, with support from GE, completed a detailed assessment of the turbine's LSBs in 2021 as part of
- 9 the "HTGS Condition Assessment and Life Extension Study." This assessment considered the results of
- major inspections and NDEs performed on the various stages of the Unit 1 turbine rotor blades as part
- of the 2021 Unit 1 major turbine overhaul project. The NDE showed a 3/8" linear crack on one of the
- 12 LSBs.

1

- 13 GE engineering provided an interim solution by welding the defective blade in the summer of 2021 and
- recommended re-inspecting the LSBs within a year of operation. The primary purpose of the re-
- inspection is to detect the initiation or propagation of cracks on the LSBs and to perform corrective
- 16 action before critical conditions are reached. GE has stated that if the crack is found again during the
- 17 next inspection, or if additional cracks are detected at that time, it would not recommend operating the
- 18 turbine until the LSBs are replaced. The next inspection is planned for the 2022 annual Unit 1 outage
- 19 and is expected to occur in June 2022. This inspection will be completed with the rotor in place via the
- 20 LP section access doors, as shown in Figure 2.
- 21 The LSBs of Units 1 and 2 turbines are approximately 53 years old. Cracking initiation indicates that the
- 22 LSBs have deteriorated to a critical condition, which could lead to failure. If additional cracking is found
- in the LSBs, it will be necessary to replace these blades to continue the safe and reliable operation of the
- 24 turbine.



- Due to the long-lead time of approximately 30 weeks to manufacture and supply the LSBs and given 1
- 2 Hydro's current commitment to have the Holyrood TGS fully available for generation until
- 3 March 31, 2024,³ this project is required to commence in 2022.

Background 2.0 4

2.1 **Existing System** 5

- 6 GE manufactured the Unit 1 and 2 turbines in 1969. The turbine consists of a high pressure ("HP")
- 7 section, an intermediate pressure ("IP") section, and a low pressure ("LP") section. Each section contains
- 8 blades mounted to the turbine rotor in rows (Figure 1). The passage of steam through the blades in each
- 9 row (stage) converts the energy of the steam into rotational energy in the turbine. The LP section is a
- 10 "parallel flow" design. The LSBs are mounted on both end rows of the LP section. Steam enters the
- 11 middle of the LP section through the crossover pipes (Figure 2) and passes through the blades in both
- 12 directions of the LP section simultaneously until reaching the LSBs. The turbine rotor is directly coupled
- 13 to the generator rotor (Figure 2 and Figure 3).




Figure 1: Turbine Rotor (Removed from Unit 1).

³ In the "Reliability and Resource Adequacy Study Review – Additional Considerations of the Labrador-Island Link Reliability Assessment and Outcomes of the Failure Investigation Findings – Additional Information," Newfoundland and Labrador Hydro, February 4, 2022, p. 7, item 3, Hydro advised the Board of Commissioners of Public Utilities of its decision to extend operation of the Holyrood TGS as a generating facility to March 31, 2024.






Figure 2: Turbine Generator




Figure 3: Turbine-Generator (with Turbine Casings Removed).

1 2.2 Operating Experience

- 2 The steam turbines at the Holyrood TGS are exposed to several degradation mechanisms such as fatigue
- 3 cracking, corrosion, erosion, wear, and creep.



- 1 Hydro performs turbine inspections on a three-year cycle and major turbine overhauls on a nine-year
- 2 cycle. The HP and IP blades can be accessed for inspection by removing the HP/IP hood (upper half of
- 3 the casing). The LSBs can be accessed for inspection by removing the access doors on the LP hood
- 4 (Figure 2). The turbine overhaul scope includes the removal of the turbine casings, rotor, diaphragms,
- 5 and bearings. Visual inspections, NDE, and any replacement or refurbishment required to ensure safe
- 6 and reliable operation are completed during the major turbine overhaul. The last major turbine
- 7 overhauls on Units 1 and 2 were completed in 2021 and 2013, respectively.
- 8 The LSBs are larger in length than other blades of the turbine LP section; therefore, they are subjected
- 9 to higher bending stresses due to the impact of steam flow. In general, statistics show that LP turbine
- 10 blades are more susceptible to failure compared to those of the HP and IP. Fatigue cracking is the main
- degradation mechanism affecting the turbine LP blades, and it takes place because of vibration arising
- 12 from the fluctuation of bending stress due to the asymmetric flow of steam through the blades. Once a
- 13 crack has been initiated, the component is assumed to have reached a critical condition of failure since
- crack growth takes place rapidly. No cracks were found on the turbine blades in previous overhauls;
- 15 however, initiation of cracking was found in 2021 on the Unit 1 LSBs. With no evidence of impact or
- other physical damage due to contact with the blade that could cause the cracking on these blades, it is
- apparent that the mode of failure is related to fatigue associated with the operating hours of the unit.
- As Unit 2 is an identical unit with a similar operating history, similar issues may be found on the Unit 2
- 19 LSBs during the scheduled overhaul in 2023.4

3.0 Analysis

20

21 3.1 Identification of Alternatives

- 22 The following alternatives were considered:
- Deferral; and
- Purchase spare turbine LSBs.

⁴ Hydro determined, in consultation with the OEM, that conducting the major overhaul earlier than currently scheduled, and incurring the associated costs, was not necessary, as there are no current indications of issues with the LSBs on Unit 2.



1 3.2 Evaluation of Alternatives

3.2.1 Deferral

- 3 The OEM has recommended that, in the event further cracking is found on Unit 1, the Unit should not
- 4 be returned to service without replacement of the LSBs. It is expected that procurement and installation
- 5 of LSBs would take approximately 42-46 weeks; should cracking occur during in-service operation of
- 6 Units 1 and 2, extensive downtime would be required.
- 7 As Hydro has committed to extend the availability of the Holyrood TGS' three units for generation until
- 8 March 31, 2024, this project must be undertaken to reduce an unacceptable risk to the safety and
- 9 reliability of the Holyrood TGS..

10 3.2.2 Purchase Spare Turbine LSBs

- 11 As the entire Unit 1 turbine LSBs have been exposed to the same operating conditions as the cracked
- 12 blade, Hydro believes it is reasonable to assume cracking on additional LSBs may be identified in future
- 13 inspections. Given that Unit 2 is of identical design and has been subjected to near-identical operating
- 14 conditions, Hydro believes procurement of spare LSBs is a prudent approach to mitigate the risk of
- 15 failure of the LSBs on either unit. As the delivery period for the LSBs is approximately 30 weeks, the
- 16 purchase of spare turbine LSBs will significantly reduce the downtime if a replacement of defective LSBs
- is required. If cracking of LSBs occurs in either Unit 1 or Unit 2 turbines and spare LSBs are available,
- 18 restoring the unit generation availability can be achieved in 12–16 weeks compared to 42–46 weeks. In
- its "HTGS Condition Assessment and Life Extension Study," Hatch acknowledged the discovery of cracks
- during the 2021 Unit 1 turbine inspection and has agreed with the OEM's recommendation to procure a
- 21 spare set of LSBs to reduce downtime in case of a blade failure.⁵

3.3 Recommended Alternative

- 23 Hydro determined that the viable alternative is the purchase of one set of turbine LSBs to be retained as
- capital spares. This spare set of LSBs can be used for Unit 1 or Unit 2 turbines at the Holyrood TGS, as
- 25 both units are identical. This alternative allows Hydro to manage the acceptable risk, maintaining the
- required generation availability of Holyrood TGS until March 31, 2024.

⁵ "HTGS Condition Assessment and Life Extension Study," Hatch Ltd., March 31, 2022, vol. I.



22

Page 5

1 4.0 Project Description

2 **4.1 Scope**

- 3 The project scope includes the procurement of one set of turbine LSBs to be held as capital spares that
- 4 can be used for either Unit 1 or Unit 2 turbines at the Holyrood TGS.

5 **4.2 Estimate**

6 The estimate for this project is shown in Table 1.

Table 1: Project Estimate (\$000)

Project Cost	2022	2023	Beyond	Total
Material Supply	0.0	1,420.0	0.0	1,420.0
Labour	11.6	1.8	0.0	13.4
Consultant	0.0	0.0	0.0	0.0
Contract Work	0.0	0.0	0.0	0.0
Other Direct Costs	5.8	0.0	0.0	5.8
Interest and Escalation	0.7	67.0	0.0	67.7
Contingency	0.9	71.1	0.0	72.0
Total	19.0	1,559.9	0.0	1,578.9

7 4.3 Schedule

8 The anticipated project schedule is shown in Table 2.

Table 2: Project Schedule

Activity	Start Date	End Date
Planning		
Prepare planning documentation	July 2022	July 2022
Procurement		
Order turbine LSBs	July 2022	July 2022
Receive turbine LSBs on site	February 2023	March 2023
Closeout		
Prepare closeout documentation	April 2023	May 2023



5.0 Conclusion

1

- 2 This project is required to procure one set of turbine LSBs for use as capital spares for Unit 1 or Unit 2
- 3 turbines at the Holyrood TGS.
- 4 The NDE of the Unit 1 turbine during its major overhaul in 2021 showed cracking of one of the LSBs. As
- 5 these blades have been in service for 53 years and all the LSBs have been exposed to the same operating
- 6 conditions, Hydro believes it is reasonable to assume that additional cracking will be initiated in the LSBs
- 7 and potentially propagated to critical failure. The failure of turbine blades while rotating at high speeds
- 8 leads to increased vibrations of the rotor. This could cause damage to turbine components and possible
- 9 leakage of steam into the powerhouse, creating a major safety hazard. Given the identical design and
- 10 similar operating conditions of Units 1 and 2, Hydro believes procurement of spare LSBs is a prudent
- approach to mitigate the risk of failure of LSBs on either unit.
- 12 This project was not considered for inclusion in Hydro's "2022 Capital Budget Application," as the
- cracking on the Unit 1 LSBs was not known at the time the application was finalized. Inclusion in Hydro's
- 14 "2023 Capital Budget Application" would not provide sufficient time to procure spare LSBs before the
- 15 Unit 2 turbine overhaul in 2023, as the turbine LSBs have a long procurement period of approximately
- 30 weeks. The purchase of spare turbine LSBs will significantly reduce the downtime if the replacement
- 17 of defective LSBs is required.
- 18 Given Hydro's current commitment to maintaining the full generation availability of the Holyrood TGS
- 19 until March 31, 2024, Hydro, is requesting approval of this supplemental capital expenditure to enable
- 20 procurement to commence in 2022.





Affidavit



IN THE MATTER OF the Electrical Power Control Act, 1994, SNL 1994, Chapter E-5.1 ("EPCA") and the Public Utilities Act, RSNL 1990, Chapter P-47 ("Act"), and regulations thereunder; and

IN THE MATTER OF an application by Newfoundland and Labrador Hydro ("Hydro") for approval to purchase one set of last stage blades ("LSB") to serve as capital spares for Units 1 and 2 at the Holyrood Thermal Generating Station ("Holyrood TGS") pursuant to s 41(3) of the Act.

AFFIDAVIT

- I, Robert Collett, of St. John's in the province of Newfoundland and Labrador, make oath and say as follows:
- I am Vice President, Engineering and NL System Operator for Newfoundland and Labrador Hydro, the applicant named in the attached application.
- 2. I have read and understand the foregoing application.
- 3. To the best of my knowledge, information, and belief, all of the matters, facts, and things set out in this application are true.

SWORN at St. John's in the Province of Newfoundland and Labrador this day of Labrador this 2022 before me:)

Barrister - Newfoundland and Labrador

Robert Collett, P. Eng.