- 1 Q. Reference: Application, paragraph 14.
- 2 Please describe the repairs necessary for the LCP genset.

4

3

The repairs necessary for the LCP¹ genset, which are minor in nature, include
replacement of the seals and gaskets to address soil and exhaust leaks. This is a
common occurrence for infrequently used diesel gensets. The aftercooler radiator and
engine radiator need to be cleaned to ensure peak cooling performance. The complete
planned maintenance package will be performed to ready the genset for use, including
an oil change, fluid level checks, adjustment of valves, visual checking of fuel lines,

-

wiring harness, and generator inspection.

<sup>&</sup>lt;sup>1</sup> Lower Churchill Project ("LCP").