

1 Q. **Reference: Volume II, Wood Pole Line Management Program - Various, Tab 11, page 7, Table 4**

2

3 Were the 11 transmission lines identified in Table 4 the only transmission lines inspected in  
4 2018?

5

6

7 A. The 11 transmission lines identified in Table 4 were the only wood pole transmission lines  
8 inspected and treated under the Wood Pole Line Management Program in 2018. In addition to  
9 the Wood Pole Line Management Program, Helicopter patrols are performed biannually on all  
10 transmission lines and regular climbing inspections were performed on the existing steel tower  
11 lines as per established inspection schedules.